

## | FAILURE MODES EFFECTS ANALYSIS (FMEA) - CIL HARDWARE

NUMBER:05-6PH-24805 -X

SUBSYSTEM NAME: EPD&amp;C - GROUND COMMAND INTERFACE LOGIC (GCIL)

REVISION: 1 08/24/97

---

**PART DATA**

---

	PART NAME	PART NUMBER
	VENDOR NAME	VENDOR NUMBER
LRU	:PANEL C3A7	VO70-730285
SRU	:TOGGLE SWITCH	ME452-0102-7201

---

**EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:**

SWITCH, S-BAND PM CONTROL. TOGGLE SWITCH, 2 POLE 2 POSITION. POSITIONS ARE CMD, PNL.

REFERENCE DESIGNATORS: 35V73A3A7S9

QUANTITY OF LIKE ITEMS: 1

ONE - 2 POLES PROVIDE DUAL REDUNDANCY

**FUNCTION:**

ENABLES GROUND (SOFTWARE) CONTROL OF THE S-BAND PM COMMUNICATIONS SYSTEM BY ENABLING ALL THE GCIL "COMMAND" DRIVERS THAT CONTROL THAT SYSTEM AND DISABLING THE CORRESPONDING "PANEL" DRIVERS THAT TRANSFER THE PANEL CONTROL SIGNALS. THIS IS DONE IN THE CMD POSITION BY SENDING TWO REDUNDANT "COMMAND" DRIVER ENABLE SIGNALS TO THE GCIL.

## FAILURE MODES EFFECTS ANALYSIS FMEA - CIL FAILURE MODE

NUMBER: 05-6PH-24805-03

REVISION#: 1 08/24/97

SUBSYSTEM NAME: EPD&amp;C - GROUND COMMAND INTERFACE LOGIC (GCIL)

LRU: PANEL C3A7

CRITICALITY OF THIS

ITEM NAME: TOGGLE SWITCH

FAILURE MODE: 2/2

## FAILURE MODE:

FAILS SHORTED TO GROUND, ANY TERMINAL SHORTS TO GROUND

## MISSION PHASE:

PL PRE-LAUNCH  
 LO LIFT-OFF  
 OO ON-ORBIT  
 DO DE-ORBIT  
 LS LANDING/SAFING

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 102 COLUMBIA  
 103 DISCOVERY  
 104 ATLANTIS  
 105 ENDEAVOUR

## CAUSE:

PIECE-PART STRUCTURAL FAILURE, CONTAMINATION, VIBRATION, MECHANICAL  
 SHOCK, PROCESSING ANOMALY

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REDUNDANCY SCREEN A) N/A  
 B) N/A  
 C) N/A

## PASS/FAIL RATIONALE:

A)

B)

C)

## REMARKS/RECOMMENDATIONS:

CORRECTING ACTION PRECLUDES USE OF THE UPLINK BLOCK SWITCH IN THE "BLOCK  
 ALL" POSITION DURING AOS PERIODS.

**FAILURE MODES EFFECTS ANALYSIS (FMEA) - CIL FAILURE MODE**  
**NUMBER: 05-6PH-24805-03**

---

**- FAILURE EFFECTS -**

---

**(A) SUBSYSTEM:**

CATASTROPHIC SWITCH FAILURE RESULTS IN LOSS OF THE TWO REDUNDANT GCIL POWER CIRCUITS (MAIN BUS CIRCUIT BREAKERS 44, 49 OPEN), WORST CASE. GCIL DRIVERS FAIL SAFE TO THE PANEL CONTROL MODE.

**(B) INTERFACING SUBSYSTEM(S):**

COMMAND CAPABILITY LOST FOR PM, FM, TV, KU AND P/L. AFTER THIS ONE FAILURE, LOSE CAPABILITY TO POWER BOTH NSP'S BY THE GCIL "COMMAND" MODE. THE NSP'S CAN ONLY BE ACTIVATED BY THE "PANEL" MODE. ONE ADDITIONAL FAILURE (NSP ACTIVATE SWITCH) IS REQUIRED BEFORE ALL CAPABILITY IS LOST FOR ACTIVATING EITHER NSP.

**(C) MISSION:**

POSSIBLE LOSS OF MISSION DUE TO MINIMUM DURATION FLIGHT DECISION AFTER LOSS OF "COMMAND" ACTIVATION OF BOTH NSP'S.

**(D) CREW, VEHICLE, AND ELEMENT(S):**

NO EFFECT - FIRST FAILURE.

**(E) FUNCTIONAL CRITICALITY EFFECTS:**

AFTER LOSS OF "COMMAND" ACTIVATION OF BOTH NSP'S THE MISSION WOULD BE REDUCED TO MDF. IF THE "PANEL" ACTIVATION OF BOTH NSP FAILED, A NEXT PLS WOULD BE DECLARED.

---

**-DISPOSITION RATIONALE-**

---

**(A) DESIGN:**

REFER TO APPENDIX A, ITEM NO. 1 - TOGGLE SWITCH

**(B) TEST:**

REFER TO APPENDIX A, ITEM NO. 1 - TOGGLE SWITCH

**GROUND TURNAROUND TEST**

ANY TURNAROUND CHECKOUT TESTING IS ACCOMPLISHED IN ACCORDANCE WITH OMRSD.

**(C) INSPECTION:**

REFER TO APPENDIX A, ITEM NO. 1 - TOGGLE SWITCH

**(D) FAILURE HISTORY:**

FAILURE MODES EFFECTS ANALYSIS (FMEA) - CIL FAILURE MODE  
NUMBER: 05-6PH-24805-03

CURRENT DATA ON TEST FAILURES, FLIGHT FAILURES, UNEXPLAINED ANOMALIES, AND OTHER FAILURES EXPERIENCED DURING GROUND PROCESSING ACTIVITY CAN BE FOUND IN THE PRACA DATA BASE.

(E) OPERATIONAL USE:

NONE NECESSARY. THE REDUNDANT GCIL POWER CIRCUIT AND SWITCH "COMMAND" DRIVER ENABLE SIGNAL PERFORM THE FUNCTION OR THE SYSTEM REVERTS TO "PANEL" CONTROL OF SYSTEM FUNCTIONS.

- APPROVALS -

EDITORIALLY APPROVED	: BNA	: <u>J. Kaminski</u> 8/24/97
EDITORIALLY APPROVED	: JSC	: <u>D. D'Amico</u> 9/30/97
TECHNICAL APPROVAL	: VIA APPROVAL FORM	96-CIL-018_05-6PH