

**FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL HARDWARE
NUMBER: M5-6SS-0909 -X**

SUBSYSTEM NAME: ISS DOCKING SYSTEM

REVISION: 0

02/27/98

PART DATA

	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
LRU	:MID POWER CONTROL ASSEMBLY 1	VO70-764400
LRU	:MID POWER CONTROL ASSEMBLY 2	VO70-764430
SRU	:FUSE	ME451-0009-1005

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

FUSE, GENERAL PURPOSE, 10 AMP - EXTERNAL AIRLOCK DOCKING BASE HEATER POWER, VESTIBULE, ZONES 1, 2, AND 3

REFERENCE DESIGNATORS: 40V76A25F11
40V76A25F13
40V76A25F17
40V76A26F11
40V76A26F13
40V76A26F17

QUANTITY OF LIKE ITEMS: 6
(SIX)

FUNCTION:

PROVIDES POWER TO A DOCKING BASE HEATER CIRCUIT. PROTECTS MAIN A(B) POWER FROM SHORTS IN THE DOCKING BASE HEATER CIRCUITS.

REFERENCE DOCUMENTS: 1) VS70-640109, SCHEMATIC DIAGRAM - AIRLOCK ENVIRONMENTAL CONTROL SUBSYSTEM

**FAILURE MODES EFFECTS ANALYSIS FMEA - NON-CIL FAILURE MODE
NUMBER: M5-6SS-0909-01**

REVISION#: 0 02/27/98

SUBSYSTEM NAME: ISS DOCKING SYSTEM
LRU: MID PCA 1(2)
ITEM NAME: FUSE

CRITICALITY OF THIS
FAILURE MODE: 1R3

FAILURE MODE:
FAILS OPEN, FAILS TO CONDUCT

MISSION PHASE: OO ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 103 DISCOVERY
104 ATLANTIS
105 ENDEAVOUR

CAUSE:
A) STRUCTURAL FAILURE, B) CONTAMINATION, C) VIBRATION, D) MECHANICAL SHOCK, E)
PROCESSING ANOMALY, F) THERMAL STRESS

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

CRITICALITY 1R2 DURING INTACT ABORT ONLY (AVIONICS ONLY)? NO

REDUNDANCY SCREEN A) PASS
B) PASS
C) PASS

PASS/FAIL RATIONALE:

A)

B)

C)

METHOD OF FAULT DETECTION:
REVIEW OF HEATER CIRCUIT TELEMETRY DATA

MASTER MEAS. LIST NUMBERS: V64T0133A
V64T0134A

**FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL FAILURE MODE
NUMBER: M5-6SS-0909-01**

CORRECTING ACTION: MANUAL

**CORRECTING ACTION DESCRIPTION:
CREW WILL ACTIVATE REDUNDANT HEATER CIRCUIT.**

- FAILURE EFFECTS -

(A) SUBSYSTEM:

FIRST FAILURE - LOSS OF POWER TO ONE HEATER CIRCUIT IN ZONE. REDUNDANT HEATER CIRCUIT IN ZONE CONTROLS TEMPERATURE WITHIN LIMITS.

(B) INTERFACING SUBSYSTEM(S):

FIRST FAILURE - NO EFFECT

(C) MISSION:

FIRST FAILURE - NO EFFECT

(D) CREW, VEHICLE, AND ELEMENT(S):

FIRST FAILURE - NO EFFECT

(E) FUNCTIONAL CRITICALITY EFFECTS:

POSSIBLE LOSS OF CREW/VEHICLE AFTER THREE FAILURES:

- 1) FUSE IN HEATER CIRCUIT (A) FAILS OPEN - LOSS OF ONE HEATER CIRCUIT IN AFFECTED ZONE. THE ASSOCIATED CIRCUIT BREAKER (A) IS OPENED AND THE REDUNDANT HEATER CIRCUIT BREAKER (B) IS CLOSED TO RESTORE HEATING IN THE AFFECTED ZONE.
- 2) GENERAL PURPOSE RELAY (B) IN REDUNDANT HEATER CIRCUIT FAILS OPEN - LOSS OF POWER TO REDUNDANT HEATERS IN ALL THREE ZONES.
- 3) CIRCUIT BREAKER (A) FAILS OPEN DURING ATTEMPT TO RE-ENERGIZE THE REMAINING INTACT (A) HEATERS RESULTING IN LOSS OF ALL HEATING CAPABILITY. POTENTIAL CONDENSATION ON EXTERNAL AIRLOCK WALLS RESULTS IN WATER IN EXTERNAL AIRLOCK. WATER MIGRATION TO KEEL AREA COULD RENDER RUSSIAN AVIONICS INOPERATIVE AFTER DOCKING, RESULTING IN LOSS OF NOMINAL AND PYROTECHNIC UNDOCKING CAPABILITY.

DESIGN CRITICALITY (PRIOR TO DOWNGRADE, DESCRIBED IN (F)):

(F) RATIONALE FOR CRITICALITY DOWNGRADE:

ALTHOUGH THE CRITICALITY REMAINS UNCHANGED AFTER WORKAROUNDS CONSIDERATION (ALLOWED PER CR S050107W), THEY ARE PROVIDING ADDITIONAL FAULT TOLERANCE TO THE SYSTEM.

**FAILURE MODES EFFECTS ANALYSIS (FMEA) – NON-CIL FAILURE MODE
NUMBER: M5-6SS-0908-01**

AFTER THE THIRD FAILURE, THE CREW WOULD PERFORM EVA TO REMOVE 96 BOLTS FROM THE DOCKING BASE TO CIRCUMVENT THE WORST CASE "DESIGN CRITICALITY" EFFECT. IF UNABLE TO PERFORM EVA (FOURTH FAILURE), POSSIBLE LOSS OF CREW/VEHICLE DUE TO LOSS OF ALL UNDOCKING CAPABILITY.

- TIME FRAME -

TIME FROM FAILURE TO CRITICAL EFFECT: DAYS

TIME FROM FAILURE OCCURRENCE TO DETECTION: HOURS

TIME FROM DETECTION TO COMPLETED CORRECTING ACTION: HOURS

**IS TIME REQUIRED TO IMPLEMENT CORRECTING ACTION LESS THAN TIME TO EFFECT?
YES**

RATIONALE FOR TIME TO CORRECTING ACTION VS TIME TO EFFECT:

DESIGN FAULT TOLERANCE: POSSIBLE LOSS OF VESTIBULE HEATING AFTER THREE FAILURES. AFTER THE THIRD FAILURE, THE CREW CAN PERFORM EVA TO REMOVE 96 BOLTS FROM THE DOCKING BASE TO UNDOCK.

HAZARD REPORT NUMBER(S): ORBI 401

HAZARD(S) DESCRIPTION:

INABILITY TO SAFELY SEPARATE ORBITER FROM A MATED ELEMENT

- APPROVALS -

SS&PAE
DESIGN ENGINEERING

T. K. KIMURA
C. J. ARROYO

T. Kimura 4-13-98
CR