

PAGE: 1

PRINT DATE: 10/10/95

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL HARDWARE  
NUMBER: M8-1MR-E006-X

SUBSYSTEM NAME: ECLSS - EXTERNAL AIRLOCK

REVISION: 2 9/15/95

	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
(LRU)	CAP, PRESSURE CARELTON TECHNOLOGIES	MC250-0004-0010 2763-2001-7

PART DATA

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:  
EXTERNAL AIRLOCK AFT HATCH EQUALIZATION VALVE PRESSURE CAP

REFERENCE DESIGNATORS:

QUANTITY OF LIKE ITEMS: 2  
TWO

FUNCTION:  
CAPS ONTO EQUALIZATION VALVE TO PROVIDE SECONDARY PROTECTION FOR  
INTERNAL LEAKAGE ACROSS EXTERNAL AIRLOCK AFT HATCH.

REFERENCE DOCUMENTS: M072-593826

PAGE: 8

PRINT DATE: 10/20/95

**FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL FAILURE MODE**

NUMBER: M8-1MR-E006-03

REVISION# 2 9/15/95

SUBSYSTEM NAME: ECLSS - EXTERNAL AIRLOCK

LRU: CAP, EQUALIZATION VALVE PRESSURE

CRITICALITY OF THIS

ITEM NAME: CAP, EQUALIZATION VALVE PRESSURE

FAILURE MODE: 1R3

**FAILURE MODE:**

INABILITY TO REMOVE

**MISSION PHASE:**

OO ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 104 ATLANTIS

**CAUSE:**

CONTAMINATION, PHYSICAL BINDING/JAMMING, CORROSION, VIBRATION, MECHANICAL SHOCK

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

CRITICALITY 1R2 DURING INTACT ABORT ONLY (AVIONICS ONLY)? N/A

**REDUNDANCY SCREEN**

A) PASS

B) N/A

C) PASS

**PASS/FAIL RATIONALE:**

A)

B)

N/A - AT LEAST TWO REMAINING PATHS ARE DETECTABLE IN FLIGHT.

C)

**METHOD OF FAULT DETECTION:**

PHYSICAL OBSERVATION

**CORRECTING ACTION:** MIR 1 - CREW COULD UTILIZE REDUNDANT EQUALIZATION VALVE TO EQUALIZE PRESSURE BETWEEN EXTERNAL AIRLOCK AND SPACELAB.

MULTI-MIR - CREW COULD UTILIZE: (1) REDUNDANT EQUALIZATION VALVE ON EXTERNAL AIRLOCK AFT HATCH. (2) INTERNAL AIRLOCK DEPRESSURIZATION VALVE, OR (3) EVA "C" HATCH EQUALIZATION VALVES TO EQUALIZE AIRLOCK/OUTSIDE PRESSURE.

**REMARKS/RECOMMENDATIONS:**

EXTERNAL AIRLOCK AFT HATCH SHOULD NOT BE OPENED IF PRESSURE BETWEEN

EXTERNAL AIRLOCK AND SPACELAB TUNNEL CANNOT BE EQUALIZED (MIR 1).

EXTERNAL AIRLOCK AFT HATCH CAN BE USED FOR EVA PURPOSES (MULTI-MIR).

PAGE: 9

PRINT DATE: 10/10/95

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL FAILURE MODE  
 NUMBER: M8-1MR-2006-03

---

- FAILURE EFFECTS -

---

**(A) SUBSYSTEM:**

LOSS OF ONE EQUALIZATION VALVE. RATE OF PRESSURE EQUALIZATION ACROSS EXTERNAL AIRLOCK AFT HATCH REDUCED. LOSS OF CAPABILITY TO EQUALIZE PRESSURE ACROSS THE EXTERNAL AIRLOCK AFT HATCH IF UNABLE TO REMOVE CAP ON BOTH EQUALIZATION VALVES.

**(B) INTERFACING SUBSYSTEM(S):**

NO EFFECT ON ORBITER INTERFACING SUBSYSTEMS.

**(C) MISSION:**

MIR 1 - NO EFFECT FIRST FAILURE. SECOND VALVE FAILURE WILL PRECLUDE SPACELAB OPERATIONS.  
 MULTI-MIR - NO EFFECT ON A NOMINAL MISSION.

**(D) CREW, VEHICLE, AND ELEMENT(S):**

MIR 1 - NO EFFECT ON CREW OR VEHICLE.  
 MULTI-MIR - NO EFFECT UNTIL ALL MEANS OF EQUALIZING EXTERNAL AIRLOCK AND OUTSIDE ATMOSPHERE IS LOST.

**(E) FUNCTIONAL CRITICALITY EFFECTS:**

FIRST FAILURE (INABILITY TO REMOVE CAP FROM FIRST EQUALIZATION VALVE) - RATE OF PRESSURE EQUALIZATION ACROSS EXTERNAL AIRLOCK AFT HATCH REDUCED.

SECOND FAILURE (INABILITY TO REMOVE CAP FROM SECOND EQUALIZATION VALVE):  
 MIR 1 - LOSS OF CAPABILITY TO EQUALIZE PRESSURE BETWEEN EXTERNAL AIRLOCK AND SPACELAB. POSSIBLE LOSS OF MISSION OBJECTIVES ASSOCIATED WITH SPACELAB IF SECOND FAILURE OCCURS PRIOR TO COMPLETION OF SPACELAB ACTIVITIES - CRITICALITY 2R3 CONDITION.

MULTI-MIR - INABILITY TO VENT OUT EXTERNAL AIRLOCK PRESSURE THROUGH THESE VALVES.

THIRD & FOURTH FAILURES (INABILITY TO OPEN BOTH EQUALIZATION VALVES ON EVA "C" HATCH) - INABILITY TO VENT OUT TUNNEL ADAPTER PRESSURE THROUGH THESE VALVES (MULTI-MIR):

FIFTH FAILURE (INTERNAL AIRLOCK DEPRESSURIZATION VALVE FAILS TO OPEN) - LOSS OF CAPABILITY TO EQUALIZE PRESSURE BETWEEN ODS AND OUTSIDE ENVIRONMENT. FAILURE TO EQUALIZE PRESSURE WILL PRECLUDE OPENING OF TUNNEL ADAPTER "C" HATCH AND EXTERNAL AIRLOCK AFT HATCH RESULTING IN THE INABILITY TO PERFORM AN EVA (MULTI-MIR).

SIXTH FAILURE (FAILURE NECESSITATES AN EVA TO CORRECT A CRIT 1 CONDITION) - POSSIBLE LOSS OF CREW AND VEHICLE - CRITICALITY 1R3 CONDITION (MULTI-MIR).

DESIGN CRITICALITY (PRIOR TO DOWNGRADE, DESCRIBED IN (F)): 2R3

**(F) RATIONALE FOR CRITICALITY DOWNGRADE:**

NONE. CRITICALITY IS BEING UPGRADED TO A 1R3 BASED ON INABILITY TO PERFORM A CONTINGENCY EVA WHEN REQUIRED.

---

- TIME FRAME -

---

TIME FROM FAILURE TO CRITICAL EFFECT: HOURS TO DAYS

TIME FROM FAILURE OCCURRENCE TO DETECTION: SECONDS

FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL FAILURE MODE  
NUMBER: M8-1MR-E005-03

TIME FROM DETECTION TO COMPLETED CORRECTIVE ACTION: SECONDS TO MINUTES

IS TIME REQUIRED TO IMPLEMENT CORRECTIVE ACTION LESS THAN TIME TO EFFECT?  
YES

RATIONALE FOR TIME TO CORRECTING ACTION VS TIME TO EFFECT:  
CREW WOULD HAVE ENOUGH TIME TO OPEN EVA 'C' HATCH EQUALIZATION VALVES  
OR INTERNAL AIRLOCK MANUAL DEPRESS VALVE TO EQUALIZE PRESSURE TO THE  
OUTSIDE ATMOSPHERE BEFORE THE NEED FOR CONTINGENCY EVA BECAME  
CATASTROPHIC.

HAZARDS REPORT NUMBER(S): DM10HA06(F)

HAZARD(S) DESCRIPTION:  
EVA HAZARD.

- APPROVALS -

PRODUCT ASSURANCE ENGR. : M. W. GUENTHER  
DESIGN ENGINEER : K. J. KELLY

*M. W. Guenther*  
*K. J. Kelly*