

**FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL HARDWARE**  
**NUMBER:M8-1SS-E035 -X**

SUBSYSTEM NAME: ECLSS - ARPCS

REVISION: 1

10/22/97

---

**PART DATA**


---

	<b>PART NAME</b>	<b>PART NUMBER</b>
	<b>VENDOR NAME</b>	<b>VENDOR NUMBER</b>
LRU	:VALVE, PURGE ISO CARLETON TECHNOLOGIES	MC250-0004-0011 2765-0001-5

---

**EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:**  
**CREW CABIN PURGE ISO VALVE**

**QUANTITY OF LIKE ITEMS:** 1  
 ONE

**FUNCTION:**

PROVIDES CAPABILITY FOR VENTING CREW CABIN PRESSURE OVERBOARD VIA A VACUUM VENT LINE. THE VALVE IS A BUTTERFLY VALVE THAT HAS TWO FLOW POSITIONS FIXED BY DETENTS IN THE ACTUATION MECHANISM. THIS VALVE IS MANUALLY OPERATED WITHIN THE CREW CABIN.

**REFERENCE DOCUMENTS:** VS28-643001  
 V828-643222  
 M072-643401

**FAILURE MODES EFFECTS ANALYSIS FMEA - NON-CIL FAILURE MODE**

**NUMBER: M8-1SS-E035-01**

**REVISION#: 0 04/08/97**

**SUBSYSTEM NAME: ECLSS - ARPCS  
LRU: VALVE, CREW CABIN PURGE ISO  
ITEM NAME: VALVE, CREW CABIN PURGE ISO**

**CRITICALITY OF THIS  
FAILURE MODE: 1R3**

**FAILURE MODE:  
FAILS TO OPEN, RESTRICTED FLOW**

**MISSION PHASE: OO ON-ORBIT**

<b>VEHICLE/PAYLOAD/KIT EFFECTIVITY:</b>	103	DISCOVERY
	104	ATLANTIS
	105	ENDEAVOUR

**CAUSE:  
CORROSION, CONTAMINATION, PHYSICAL BINDING/JAMMING, EXCESSIVE VIBRATION,  
MECHANICAL SHOCK, MATERIAL DEFECT, FATIGUE**

**CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO**

<b>REDUNDANCY SCREEN</b>	<b>A) PASS</b>
	<b>B) PASS</b>
	<b>C) PASS</b>

**PASS/FAIL RATIONALE:**

**A)**

**B)**

**C)**

**METHOD OF FAULT DETECTION:**

**INSTRUMENTATION - LOSS OF VENTING OF PRESSURE TO OUTSIDE WHEN CREW  
CABIN PURGE VALVE AND ECLSS BAY VACUUM VENT ISO VALVE ARE OPEN. PHYSICAL  
OBSERVATION - VALVE DOES NOT OPEN WHEN MANUALLY OPERATED.**

**CORRECTING ACTION: MANUAL**

**CORRECTING ACTION DESCRIPTION:**

**WITH 576 BULKHEAD HATCH OPEN CREW COULD UTILIZE THE EXTERNAL AIRLOCK  
DEPRESS VALVE OR ONE OR BOTH EQUALIZATION VALVES ON THE EXTERNAL**

**FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL FAILURE MODE  
NUMBER: M8-1SS-E035-01**

AIRLOCK AFT HATCH (WHEN NO PRESSURIZED PAYLOAD IS INSTALLED) OR ONE OR BOTH EQUALIZATION VALVES ON THE TUNNEL ADAPTER "C" HATCH (WHEN PRESSURIZED PAYLOAD IS INSTALLED) TO VENT PRESSURE (FROM CREW CABIN AND ODS) OVERBOARD. ADDITIONAL CAPABILITY TO VENT PRESSURE IS AVAILABLE WHEN ORBITER AND SPACE STATION ARE NOT DOCKED BY THE USE OF ONE OR BOTH EQUALIZATION VALVES ON EXTERNAL AIRLOCK UPPER HATCH.

**REMARKS/RECOMMENDATIONS:**

VALVE IS ONLY UTILIZED TO VENT PRESSURE TO THE OUTSIDE IN THE EVENT SMOKE, EXCESSIVE OXYGEN, OR OTHER TOXIC FUMES ARE PRESENT IN THE CREW CABIN. FILTER PROVIDED WITHIN SERIES PURGE VALVE WILL HELP SCREEN OUT CONTAMINATES. PURGE ISO VALVE DOES NOT CONTAIN A FILTER.

---

**- FAILURE EFFECTS -**

---

**(A) SUBSYSTEM:**

LOSS OF FUNCTION - VALVE CANNOT BE USED TO VENT CREW CABIN PRESSURE OVERBOARD.

**(B) INTERFACING SUBSYSTEM(S):**

NO EFFECT UNTIL CREW CABIN VENTING IS REQUIRED. THEN USE OF CONTINGENCY ACTION TO PERFORM VENTING WOULD RESULT IN AN INCREASED USE OF CONSUMABLES.

**(C) MISSION:**

NO IMMEDIATE EFFECT. FAILURE TO REMOVE CONTAMINANTS FROM CREW CABIN AIR COULD RESULT IN EARLY MISSION TERMINATION.

**(D) CREW, VEHICLE, AND ELEMENT(S):**

NO EFFECT UNTIL SMOKE, EXCESSIVE OXYGEN, OR OTHER TOXIC FUMES ARE PRESENT IN THE CREW CABIN. THEN LOSS OF ALL CREW CABIN VENTING CAPABILITIES COULD JEOPARDIZE THE SAFETY OF THE CREW.

**(E) FUNCTIONAL CRITICALITY EFFECTS:**

FIRST FAILURE (CREW CABIN PURGE ISO VALVE FAILS TO OPEN OR CLOGGED) - INABILITY TO VENT CREW CABIN PRESSURE OVERBOARD USING THIS VALVE.  
SECOND FAILURE (EXTERNAL AIRLOCK DEPRESS VALVE FAILS TO OPEN) - INABILITY TO DEPRESSURIZE EXTERNAL AIRLOCK FOR VENTING OF CREW CABIN AND ODS PRESSURE OVERBOARD WITH 576 BULKHEAD HATCH OPEN.  
THIRD FAILURE (FIRST EQUALIZATION VALVE ON AN OUTSIDE HATCH FAILS TO OPEN) - NO EFFECT OTHER THAN VENTING TIME INCREASED WHEN USING A SINGLE EQUALIZATION VALVE TO VENT PRESSURE OVERBOARD.

**FAILURE MODES EFFECTS ANALYSIS (FMEA) - NON-CIL FAILURE MODE  
NUMBER: M8-1SS-E035-01**

FOURTH FAILURE (SECOND EQUALIZATION VALVE ON AN OUTSIDE HATCH FAILS TO OPEN) - LOSS OF ALL CREW CABIN AND ODS PRESSURE VENTING CAPABILITIES. NO EFFECT UNTIL A HAZARDOUS CONTAMINATION EXISTS.

FIFTH FAILURE (FAILURE RESULTING IN THE PRESENCE OF A TOXIC/HAZARDOUS MATERIAL WITHIN THE CREW CABIN) - THEN INABILITY TO REMOVE THIS HAZARDOUS/TOXIC CONTAMINATION FROM THE CREW CABIN COULD POTENTIALLY RESULT IN LOSS OF CREW. - CRITICALITY 1R3 CONDITION.

**DESIGN CRITICALITY (PRIOR TO DOWNGRADE, DESCRIBED IN (F)): 1R3**

**(F) RATIONALE FOR CRITICALITY DOWNGRADE:**

NONE. ALL WORKAROUNDS HAVE ALREADY BEEN CONSIDERED IN DETERMINING THE CRITICALITY OF THIS FAILURE MODE.

---

**- TIME FRAME -**

---

**TIME FROM FAILURE TO CRITICAL EFFECT: DAYS**

**TIME FROM FAILURE OCCURRENCE TO DETECTION: SECONDS**

**TIME FROM DETECTION TO COMPLETED CORRECTING ACTION: MINUTES**

**IS TIME REQUIRED TO IMPLEMENT CORRECTING ACTION LESS THAN TIME TO EFFECT?  
YES**

**RATIONALE FOR TIME TO CORRECTING ACTION VS TIME TO EFFECT:  
CREW HAS ENOUGH TIME TO UTILIZE OTHER DEPRESS/EQUALIZATION VALVES TO DEPRESSURIZE CREW CABIN BEFORE PROBLEM BECOMES CATASTROPHIC.**

**HAZARD REPORT NUMBER(S): ORBI 044**

**HAZARD(S) DESCRIPTION:**

UNKNOWN GASEOUS CONTAMINATION LEVELS IN CREW CABIN.

---

**- APPROVALS -**

---

SS & PAE  
DESIGN ENGINEER

: M. W. GUENTHER  
: K. J. KELLY

: *Max Guenther*  
: *K. J. Kelly*