

PAGE: 1

FAILURE MODES EFFECTS ANALYSIS (FMEA) NUMBER: P7-2B-CRWS-X

SUBSYSTEM NAME: SIDE HATCH JETTISON

REVISION : 09/12/88

CLASSIFICATION NAME PART NUMBER
LRU : HINGE SEVERANCE ASSEMBLY MC325-0043

QUANTITY OF LIKE ITEMS: 2

DESCRIPTION/FUNCTION:

THE HINGE SEVERANCE ASSEMBLY CONSISTS OF AN OUTER/INNER CHARGE HOLDER WITH ASSOCIATED LINEAR SHAPED CHARGE (LSC). EACH HINGE OF THE SIDE HATCH IS FITTED WITH ONE INNER CHARGE HOLDER (CONTAINING TWO SEPARATE LSC'S) AND TWO OUTER CHARGE HOLDERS EACH CONTAINING A SINGLE LSC.

PAGE: 2

PRINT DATE: 09/12/8

FAILURE MODES EFFECTS ANALYSIS (FMEA) NUMBER: P7-2B-CRW5-X

SUMMARY

SUBSYSTEM NAME: SIDE MATCH JETTISON
LRU :HINGE SEVERANCE ASSEMBLY
LRU PART #: MC325-0043
ITEM NAME:HINGE SEVERANCE ASSEMBLY

FMEA NUMBER	ABBREVIATED FAILURE MODE DESCRIPTION	CIL FLG	CRIT	MO FL
P7-2B-CRW5-01	NO OUTPUT OR FAILS OFF	X	1	1

PAGE: 3

FAILURE MODES EFFECTS ANALYSIS (FMEA) NUMBER: P7-2B-CRWS-01

REVISION: 09/12/88

SUBSYSTEM: SIDE HATCH JETTISON
LRU :HINGE SEVERANCE ASSEMBLY
ITEM NAME: HINGE SEVERANCE ASSEMBLY

CRITICALITY OF THIS
FAILURE MODE:1 1

FAILURE MODE:
LOW/NO OUTPUT FROM OUTER LSC (FAILS TO SEVER)

MISSION PHASE:
RTLS RETURN TO LAUNCH SITE
TAL TRANS ATLANTIC ABORT
AOA ABORT ONCE AROUND
DO DE-ORBIT
LS LANDING SEQUENCE

VEHICLE/PAYLOAD/KIT EFFECTIVITY:	102	COLUMBIA
	103	DISCOVERY
	104	ATLANTIS
	105	NEW ORBITER

CAUSE:
EXCESSIVE GAP, CONTAMINATION OF PYRO MIX, IMPROPER CORE LOADING.
FAILURE OF LSC OR BOOSTER CHARGE TO DETONATE, OVERSTRENGTH MATERIAL.

CRITICALITY 1/1 DURING ANY MISSION PHASE OR ABORT? YES
AOA ABORT ONCE AROUND
DO DE-ORBIT
LS LANDING SEQUENCE
RTLS RETURN TO LAUNCH SITE
TAL TRANS ATLANTIC ABORT

REDUNDANCY SCREEN A) N/A
B) N/A
C) N/A

PASS/FAIL RATIONALE:
A)
B)
C)

METHOD OF FAULT DETECTION:
NONE.

CORRECTING ACTION: NONE
NO CORRECTIVE ACTION POSSIBLE.

PAGE: 4

PRINT DATE: 09/22/8

FAILURE MODES EFFECTS ANALYSIS (FMEA) NUMBER: P7-2B-CRW5-01

- FAILURE EFFECTS -

(A) SUBSYSTEM:

LOSS OF OUTER CUTTING FUNCTION RESULTS IN A FAILURE TO SEVER THE HINGE.

(B) INTERFACING SUBSYSTEM(S):

INABILITY TO JETTISON HATCH DURING CREW EMERGENCY ESCAPE.

(C) MISSION:

NONE

(D) CREW, VEHICLE, AND ELEMENT(S):

A FAILURE OF ANY OUTER CUTTER ASSEMBLY COULD RESULT IN LOSS OF CREW DUE TO INABILITY TO EGRESS FROM THE ORBITER.

Criticality/

Required Fault Tolerance/Achieved Fault Tolerance: 1/1/0 :

RATIONALE FOR CRITICALITY:

DEVELOPMENTAL TESTS HAVE DEMONSTRATED THAT THE INNER HINGE CUTTER ASSEMBLY IS NOT REDUNDANT TO THE OUTER CUTTER ASSEMBLY. THE CORRECT OPERATION OF THE INNER ASSEMBLY IS EXCEEDINGLY SENSITIVE TO TIME DIFFERENCES IN LSC INITIATION (DEVELOPMENTAL TEST FAILURE WAS DUE TO A DIFFERENCE IN THE MICROSECOND RANGE). IF THE ARRIVAL TIMES OF THE DETONATING SIGNAL TO THE TWO LSC'S IN AN INNER ASSEMBLY ARE NOT WITHIN APPROXIMATELY TWO MICROSECONDS, THE FIRST LSC TO IGNITE RENDERS THE SECOND LSC INOPERABLE.

A SINGLE OUTER CUTTER FAILURE (TRANSFER BOOSTER ASSEMBLY, LSC) COMBINED WITH A CORRESPONDING INOPERABLE INNER LSC WOULD RESULT IN A FAILURE TO SEVER THAT HINGE. ANY DIFFERENCE IN ETS LENGTH AND/OR DETONATING SIGNAL VELOCITY (ETS SPECIFICATION ALLOWS FOR A RANGE OF ACCEPTABLE VELOCITIES RESULTS IN A DIFFERENCE IN LSC INITIATION TIME, THUS THE CURRENT HINGE SEVERANCE SYSTEM CANNOT BE CERTIFIED AS REDUNDANT.

TIME FROM FAILURE TO CRITICAL EFFECT: IMMEDIATE

TIME FROM FAILURE OCCURRENCE TO DETECTION: IMMEDIATE

TIME FROM DETECTION TO COMPLETED CORRECTIVE ACTION: N/A

TIME REQUIRED TO IMPLEMENT CORRECTIVE ACTION LESS THAN TIME TO EFFECT? N/A

PAGE: 5

PRINT DATE: 09/12/8

FAILURE MODES EFFECTS ANALYSIS (FMEA) NUMBER: P7-2B-CRW5-01

NO CORRECTIVE ACTION POSSIBLE.

- DISPOSITION RATIONALE -

(A) DESIGN:

SYSTEM PERFORMS CUTTING FUNCTION WITH NORMAL CORE LOAD. DOES NOT MEET DESIGN REQUIREMENT FOR 85% MARGIN.

(B) TEST:

PRIOR TO STS-26

QUALIFICATION TESTS - RANDOM VIBRATION, THERMAL CYCLE, PRESSURE CYCLE, SHOCK, SALT FOG, NOMINAL FIRINGS (3 AT +10 DEGREES F, 1 AT AMBIENT, 3 AT +125 DEGREES F)

ACCEPTANCE TESTS - EXAMINATION OF PRODUCT, X-RAY, N-RAY, LEAK TEST, EXPLOSIVE CORD CORE LOAD AND SEVERANCE TESTS, ENVIRONMENTAL SEAL TEST, RANDOM SAMPLE FIRING TESTS (QUAL TEST FIRINGS FULFILL REQUIREMENT FOR FIRST LOT).

SYSTEM TEST: ONE (1) INTEGRATED SYSTEM TEST.

LONG TERM

SYSTEM TEST: FIVE ADDITIONAL (5) INTEGRATED SYSTEM TESTS.

(C) INSPECTION:

RECEIVING INSPECTION

RAW MATERIAL IS VERIFIED BY INSPECTION TO ASSURE SPECIFIC SHUTTLE REQUIREMENTS ARE SATISFIED.

CONTAMINATION CONTROL

CONTAMINATION CONTROL AND CORROSION PROTECTION PROCESSES VERIFIED BY INSPECTION.

ASSEMBLY/INSTALLATION

OPERATIONS VERIFIED BY NIPS ON SHOP TRAVELER.

NONDESTRUCTIVE EVALUATION

PARTS ARE X-RAYED AND N-RAYED TO VERIFY CORRECT ASSEMBLY AND PRESENCE OF ALL DETAIL PARTS AND EXPLOSIVES. X-RAYS AND N-RAYS ARE REVIEWED BY VENDOR, DCAS, NASA QUALITY AND ENGINEERING. ALL CRITICAL DIMENSIONS ARE INSPECTED.

TEST

ATP IS VERIFIED BY INSPECTION.

CRITICAL PROCESSES

CRITICAL PROCESSES SUCH AS WELDING, PLATING, HEAT TREATING, PASSIVATION

PAGE: 6

PRINT DATE: 09/12/88

FAILURE MODES EFFECTS ANALYSIS (FMEA) NUMBER: P7-2B-CRW5-01

AND ANODIZING ARE VERIFIED BY INSPECTION.

STORAGE

STORAGE ENVIRONMENT VERIFIED BY INSPECTION.

HANDLING AND PACKAGING

HANDLING AND PACKAGING IS VERIFIED BY INSPECTION PER THE REQUIREMENTS OF APPLICABLE SPECIFICATIONS.

(D) FAILURE HISTORY:

DEVELOPMENT TEST DEMONSTRATED FAILURE TO CUT HINGE AT 85% EXPLOSIVE LOADING.

(E) OPERATIONAL USE:

ON GROUND, OVERHEAD WINDOW COULD BE UTILIZED AS AN ALTERNATE MEANS OF ESCAPE.

REMARKS:

- APPROVALS -

RELIABILITY ENGINEERING:	C. FERRARELLA	: C.F. Ferrarella RGL 9/13/88
DESIGN ENGINEERING	: R. YEE	: R. Yee RGL 9/13/88
QUALITY ENGINEERING	: E. GUTIERREZ	: E. Gutierrez RGL 9-27-88
NASA RELIABILITY	:	: Thomas Johnson 9-27-88
NASA DESIGN	:	: [Signature]
NASA QUALITY ASSURANCE	:	: [Signature]