

FAILURE MODES EFFECTS ANALYSIS FMEA - CIL FAILURE MODE

NUMBER: 05-6-2660-02

REVISION#: 2 07/26/99

SUBSYSTEM NAME: ELECTRICAL POWER DISTRIBUTION & CONTROL

LRU: PANEL F6A8 (PRE-MEDS), F6A4 (MEDS)

CRITICALITY OF THIS

ITEM NAME: SWITCH, ROTARY

FAILURE MODE: 1R2

FAILURE MODE:

FAILS CLOSED, BROKEN SHAFT WITH DETENT FEEL REMAINING

MISSION PHASE:LO LIFT-OFF
DO DE-ORBIT**VEHICLE/PAYLOAD/KIT EFFECTIVITY:**102 COLUMBIA
103 DISCOVERY
104 ATLANTIS
105 ENDEAVOUR**CAUSE:**PIECE PART STRUCTURAL FAILURE, CONTAMINATION, VIBRATION, MECHANICAL SHOCK,
PROCESSING ANOMALY**CRITICALITY 1/1 DURING INTACT ABORT ONLY? YES**AOA ABORT ONCE AROUND
RTLs RETURN TO LAUNCH SITE
TAL TRANS-ATLANTIC LANDING**REDUNDANCY SCREEN**A) PASS
B) FAIL
C) PASS**PASS/FAIL RATIONALE:**

A)

B)

} FAILS "B" SCREEN BECAUSE TIME FOR CORRECTIVE ACTION EXCEEDS TIME TO EFFECT.

C)

- FAILURE EFFECTS -**(A) SUBSYSTEM:**

NO EFFECT

**FAILURE MODES EFFECTS ANALYSIS (FMEA) – CIL FAILURE MODE
NUMBER: 05-6-2660- 02**

(B) INTERFACING SUBSYSTEM(S):

IF THE SHAFT BREAKS WHILE MOVING THE SWITCH OUT OF THE "OFF" DETENT, THE ABILITY TO PLACE THE ROTARY SWITCH IN THE DESIRED POSITION MAY BE LOST.

(C) MISSION:

NO EFFECT

(D) CREW, VEHICLE, AND ELEMENT(S):

CRIT 1R2 FOR EMERGENCY DEORBITS. AFTER FIRST FAILURE (WHICH CAUSES THE EMERGENCY SITUATION), POSSIBLE LOSS OF COMMANDER DUE TO INABILITY TO PERFORM EMERGENCY FUNCTION ("BAILOUT" SOFTWARE ENGAGE) AND PROVIDE HIMSELF WITH A STABLE FLYING CONDITION FROM WHICH TO EGRESS WHEN INSUFFICIENT VEHICLE ENERGY IS AVAILABLE TO REACH PLANNED RUNWAY. CRIT 1/1 FOR RTLS, TAL, AND AOA ABORTS.

ALSO, POSSIBLE LOSS OF CREW/VEHICLE VIA THE FOLLOWING SCENARIO:

(1) FAILURE OF THE ROTARY SWITCH IN THE "OFF" POSITION FOR AN RTLS ABORT OR IN A POSITION OTHER THAN THE DESIRED POSITION FOR TAL OR ATO ABORTS, AND (2,3) LOSS OF CAPABILITY TO INITIATE ANY ABORT MODE VIA EITHER OF TWO KEYBOARD UNITS, RESULTING IN THE LOSS OF CAPABILITY TO EFFECT A SAFE ORBITER LANDING UNDER ASCENT ABORT CONDITIONS.

IN THE PRECEDING SCENARIO, THE ROTARY SWITCH FAILURE IS FUNCTIONAL CRITICALITY "1R" AND HARDWARE CRITICALITY "3" RATHER THAN THE "1R2" CRITICALITY WHICH IS ASSIGNED DUE TO THE EMERGENCY BAILOUT FUNCTION.

(E) FUNCTIONAL CRITICALITY EFFECTS:

-DISPOSITION RATIONALE-

(A) DESIGN:

REFER TO APPENDIX A, ITEM NO. 2 - ROTARY SWITCH

(B) TEST:

REFER TO APPENDIX A, ITEM NO. 2 - ROTARY SWITCH

GROUND TURNAROUND TEST

ANY TURNAROUND CHECKOUT TESTING IS ACCOMPLISHED IN ACCORDANCE WITH OMRSD.

**FAILURE MODES EFFECTS ANALYSIS (FMEA) -- CIL FAILURE MODE
NUMBER: 05-6-2560- 02**

(C) INSPECTION:
REFER TO APPENDIX A, ITEM NO. 2 - ROTARY SWITCH

(D) FAILURE HISTORY:
CURRENT DATA ON TEST FAILURES, FLIGHT FAILURES, UNEXPLAINED ANOMALIES, AND OTHER FAILURES EXPERIENCED DURING GROUND PROCESSING ACTIVITY CAN BE FOUND IN THE PRACA DATABASE.

(E) OPERATIONAL USE:
THE ROTARY ABORT SWITCH IN CONJUNCTION WITH THE ABORT PUSHBUTTON SWITCH IS PRIME FOR SELECTING RTLS, ATO, AND TAL ABORTS AND IS THE ONLY MEANS OF ENGAGING THE "BAILOUT" MODE. RECOVERY FROM INADVERTENT SELECTION OF THE ATO ABORT WHEN ATTEMPTING THE TAL ABORT CAN BE ACCOMPLISHED VIA THE KEYBOARD.

- APPROVALS -

EDITORIALLY APPROVED	: BNA	: <u>J. Kamara 7-26-99</u>
TECHNICAL APPROVAL	: VIA APPROVAL FORM	: 96-CIL-026_05-6