

PAGE: 1

PRINT DATE: 12/19/89

SHUTTLE CRITICAL ITEMS LIST - ORBITER NUMBER: 05-6JB-20128-X

SUBSYSTEM NAME: EPD&C - MAIN PROPULSION

REVISION : 2 12/19/89

---

	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
LRU :	MID PCA 1	V070-764400
LRU :	MID PCA 3	V070-764450
SRU :	DIODE	JANTXV1N4246

---

EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:  
DIODE, BLOCKING (1 AMP), LH2 RELIEF SHUTOFF VALVE, CLOSE SWITCH SCAN.

REFERENCE DESIGNATORS: 40V76A27A1CR29  
: 40V76A25A5CR8  
: 40V76A25A5CR10

QUANTITY OF LIKE ITEMS: 3  
THREE

6 HXN 11/19/90

FUNCTION:  
ISOLATES CONTROL BUSES AND CLOSE COMMANDS IN THE SWITCH SCAN CIRCUIT.

PAGE: 2

PRINT DATE: 12/19/89

SHUTTLE CRITICAL ITEMS LIST - ORBITER

NUMBER: 05-6JB-2012B-02 HXN 1/4/90

SUBSYSTEM: EPD&C - MAIN PROPULSION

REVISION# 2 12/19/89

LRU :MID PCA 1, 3 HXN

CRITICALITY OF THIS  
FAILURE MODE:1R3

ITEM NAME: DIODE 14190

FAILURE MODE:  
SHORT (END TO END)

MISSION PHASE:  
LO LIFT-OFF

VEHICLE/PAYLOAD/KIT EFFECTIVITY: 102 COLUMBIA  
: 103 DISCOVERY  
: 104 ATLANTIS

CAUSE:  
STRUCTURAL FAILURE (MECHANICAL STRESS, VIBRATION), CONTAMINATION,  
ELECTRICAL STRESS, THERMAL STRESS, PROCESSING ANOMALY.

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

REUNDANCY SCREEN A) PASS  
B) FAIL  
C) PASS

PASS/FAIL RATIONALE:

A)

B)

FAILS B SCREEN BECAUSE NO INSTRUMENTATION IS AVAILABLE TO DETECT  
FAILURE.

C)

- FAILURE EFFECTS -

(A) SUBSYSTEM:

LOSS OF MANUAL SWITCH CLOSE COMMAND AND CONTROL BUS ISOLATION.  
DEGRADATION OF REDUNDANCY AGAINST INAOVERTENT POWER TO CLOSE SOLENOID  
OF LH2 RELIEF SHUTOFF VALVE.

(B) INTERFACING SUBSYSTEM(S):

NO EFFECT - FIRST FAILURE.

SHUTTLE CRITICAL ITEMS LIST - ORBITER

NUMBER: 05-6JB-2012B-~~02~~

(C) MISSION:  
NO EFFECT - FIRST FAILURE.

(D) CREW, VEHICLE, AND ELEMENT(S):  
NO EFFECT - FIRST FAILURE.

(E) FUNCTIONAL CRITICALITY EFFECTS:

IR/3, 2 SUCCESS PATHS AFTER FIRST FAILURE. TIME FRAME - POST MECO.

- 1) DIODE SHORTS.
- 2) SWITCH CONTACT-TO-CONTACT SHORT OF EITHER CLOSE COMMAND, RESULTING IN LOSS OF CAPABILITY TO OPEN LH2 RELIEF SHUTOFF VALVE (PVB).
- 3) EITHER LH2 RTLS DUMP VALVE (PV17,18) FAILS TO REMAIN OPEN THE FULL TIME IT IS COMMANDED FROM MECO +10 TO MECO +90 SECONDS.

RESULTS IN LACK OF RELIEF CAPABILITY PRIOR TO DUMP. POSSIBLE RUPTURE OF THE LH2 MANIFOLD CAUSING LH2 LEAKAGE INTO THE AFT COMPARTMENT, OVERPRESSURIZATION, AND FIRE/EXPLOSION HAZARD. POSSIBLE LOSS OF ADJACENT CRITICAL COMPONENTS DUE TO CRYOGENIC EXPOSURE. POSSIBLE LOSS OF CREW/VEHICLE.

SOFTWARE CR 89399 EXTENDED THE RTLS DUMP VALVE OPEN TIME TO MECO +90 SECONDS, WHICH IS SUFFICIENT DURATION TO PROVIDE A REDUNDANT RELIEF PATH PRIOR TO INITIATION OF DUMP. NOTE RESIDUALS FOLLOWING RTLS/TAL ABORT WILL BE SUFFICIENT TO REQUIRE RELIEF SYSTEM OPERATION (RTLS/TAL ABORT CRITICAL).

FAILS B SCREEN BECAUSE NO INSTRUMENTATION IS AVAILABLE TO DETECT FAILURE.

-----  
- DISPOSITION RATIONALE -  
-----

(A) DESIGN:  
REFER TO APPENDIX F, ITEM NO. 3 - DIODE, AXIAL LEAD.

(B) TEST:  
REFER TO APPENDIX F, ITEM NO. 3 - DIODE, AXIAL LEAD.

GROUND TURNAROUND TEST  
COMPLETE ELECTRICAL VERIFICATION V41A80.080A, E, EVERY FLIGHT.

(C) INSPECTION:  
REFER TO APPENDIX F, ITEM NO. 3 - DIODE, AXIAL LEAD.

(D) FAILURE HISTORY:  
REFER TO APPENDIX F, ITEM NO. 3 - DIODE, AXIAL LEAD.

(E) OPERATIONAL USE:

LH2 MANIFOLD PRESSURE IS ON CAUTION AND WARNING.

POST MECO/PRE DUMP: START MPS PROPELLANT DUMP AS SOON AS POSSIBLE.

POST DUMP: OPEN THE LH2 FILL/DRAIN VALVES.

- APPROVALS -

RELIABILITY ENGINEERING: D. DEFENSOR  
 DESIGN ENGINEERING : J. BROWN  
 QUALITY ENGINEERING : O. MASAI  
 NASA RELIABILITY :  
 NASA SUBSYSTEM MANAGER :  
 NASA EPD&C RELIABILITY :  
 NASA QUALITY ASSURANCE :  
 NASA EPD&C SUBSYS MGR :

: AT Michael C. Hon  
 : William K. Bell  
 : John J. Korman  
 : James H. Brown 1/2/90  
 : John 3/2/90  
 : Del 1/4/90 HXN 1/4/90  
 : Al  
 : Francis Bell 1/29/90