

PAGE: 1

PRINT DATE: 02/06/90

SHUTTLE CRITICAL ITEMS LIST - ORBITER NUMBER: 05-6J-2062-X

SUBSYSTEM NAME: EPD&amp;C - MAIN PROPULSION (03-1)

REVISION : 1 02/05/90

	PART NAME VENDOR NAME	PART NUMBER VENDOR NUMBER
■ LRU :	MID PCA 1	V070-764400
■ LRU :	MID PCA 3	V070-764450
■ SRU :	CONTROLLER, HYBRID DRIVER	MC477-0263-0002

■ EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

CONTROLLER, HYBRID DRIVER (HDC), TYPE III, LH2 RELIEF SHUTOFF VALVE  
CLOSE SOLENOID.

■ REFERENCE DESIGNATORS: 40V76A27AR29  
: 40V76A25AR48

■ QUANTITY OF LIKE ITEMS: 2  
TWO

■ FUNCTION:

CONDUCTS POWER TO CLOSE SOLENOID IN EACH REDUNDANT CIRCUIT FOR LH2  
RELIEF SHUTOFF VALVE. HDC IS IN SERIES WITH A DIODE AND A RPC IN EACH  
CIRCUIT.

PAGE: 6

PRINT DATE: 02/06/90

SHUTTLE CRITICAL ITEMS LIST - ORBITER NUMBER: 05-6J-2062-02

REVISION# 1 02/05/90

SUBSYSTEM: EPD&amp;C - MAIN PROPULSION (03-1)

LRU :MID PCA 1 ~~2~~ 3

ITEM NAME: CONTROLLER, HYBRID DRIVER

CRITICALITY OF THIS  
FAILURE MODE:1R3

- FAILURE MODE:  
INADVERTENT OUTPUT, FAILS "ON", FAILS TO TURN "OFF"

## MISSION PHASE:

LO LIFT-OFF

- VEHICLE/PAYLOAD/KIT EFFECTIVITY: 102 COLUMBIA  
: 103 DISCOVERY  
: 104 ATLANTIS

- CAUSE:  
PIECE PART FAILURE, CONTAMINATION, VIBRATION, MECHANICAL SHOCK,  
PROCESSING ANOMALY, THERMAL STRESS.

- CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

- REDUNDANCY SCREEN A) PASS  
B) FAIL  
C) PASS

## PASS/FAIL RATIONALE:

- A)
- B)  
FAILS B SCREEN DUE TO SERIES CIRCUIT CONFIGURATION.
- C)

## - FAILURE EFFECTS -

- (A) SUBSYSTEM:  
DEGRADATION OF REDUNDANCY AGAINST PREMATURE ACTUATION OF CLOSE SOLENOID.
- (B) INTERFACING SUBSYSTEM(S):  
NO EFFECT - FIRST FAILURE. SERIES RPC PREVENTS INADVERTENT POWER TO LP2 RELIEF SHUTOFF VALVE CLOSE SOLENOID.
- (C) MISSION:  
NO EFFECT - FIRST FAILURE.

PAGE: 6

PRINT DATE: 02/06/90

## SHUTTLE CRITICAL ITEMS LIST - ORBITER NUMBER: 05-6J-2062-02

- (D) CREW, VEHICLE, AND ELEMENT(S):  
NO EFFECT - FIRST FAILURE.

- (E) FUNCTIONAL CRITICALITY EFFECTS:

1R/3, 2 SUCCESS PATHS AFTER FIRST FAILURE. TIME FRAME - ASCENT.

1) HOC FAILS "ON".

2) SERIES R9C FAILS "ON" CAUSING LOSS OF CAPABILITY TO OPEN LH2 RELIEF SHUTOFF VALVE (PV8).

3) ONE OF THE TWO RTLS DUMP VALVES (PV17, 18) FAILS TO OPEN/REMAIN OPEN FROM MECO + 10 TO MECO + 90 SECONDS.

RESULTS IN LACK OF RELIEF/<sup>LH2</sup>CAPABILITY PRIOR TO DUMP, POSSIBLE RUPTURE OF THE LH2 MANIFOLD CAUSING LEAKAGE INTO AFT COMPARTMENT, OVERPRESSURIZATION, AND FIRE/EXPLOSION HAZARD. POSSIBLE LOSS OF ADJACENT CRITICAL COMPONENTS DUE TO CRYOGENIC EXPOSURE.

POSSIBLE LOSS OF CREW/VEHICLE.

-----  
- DISPOSITION RATIONALE -  
-----

- (A) DESIGN:

REFER TO APPENDIX B, ITEM NO. 1 - HYBRID DRIVER CONTROLLER.

- (B) TEST:

REFER TO APPENDIX B, ITEM NO. 1 - HYBRID DRIVER CONTROLLER.

GROUND TURNAROUND TEST

COMPLETE ELECTRICAL VERIFICATION VALABO.0801, EVERY FLIGHT.

- (C) INSPECTION:

REFER TO APPENDIX B, ITEM NO. 1 - HYBRID DRIVER CONTROLLER.

- (D) FAILURE HISTORY:

REFER TO APPENDIX B, ITEM NO. 1 - HYBRID DRIVER CONTROLLER.

- (E) OPERATIONAL USE:

LH2 MANIFOLD PRESSURE IS ON CAUTION AND WARNING.

POST MECO/PRE DUMP: START MPS PROPELLANT DUMP AS SOON AS POSSIBLE.

POST DUMP: OPEN THE LH2 FILL/DRAIN VALVES.

PAGE: 7

PRINT DATE: 02/06/90

SHUTTLE CRITICAL ITEMS LIST - ORBITER

NUMBER: 05-6J-2062-02

## - APPROVALS -

RELIABILITY ENGINEER	: S. TRUJILLO	: <u>St</u> 2-8-90
RELIABILITY SUPERVISOR	: M.L. HOVE	: <u>Thomas Clifton</u>
DESIGN ENGINEER	: J.L. PECK	:
DESIGN SUPERVISOR	: T.J. TAUFER	: <u>T.J. Tauffer</u> 2-9-90
QUALITY ENGINEER	: D. MASAI	: <u>D. Masai</u>
QUALITY SUPERVISOR	: J.T. COURSEN	: <u>J.T. Courson</u> 2-9-90
NASA RELIABILITY	:	: <u>R. Vancott</u> 3/2/90
NASA SUBSYSTEM MANAGER	:	: <u>J. S. S. S.</u> 3/2/90
NASA EPD&C RELIABILITY	:	: <u>John Woodard</u> 3/2/90
NASA QUALITY ASSURANCE	:	: <u>C. H. H.</u> 2/20/90
NASA EPD&C SUBSYS MGR	:	: <u>Carroll D. ... for F. Blair</u> 3/5/90