

SSMIE FMEA/CIL
REDUNDANCY SCREEN

Component Group: Combustion Devices
CIL Item: A200-07
Part Number: RS009122
Component: Main Injector
FMEA Item: A200
Failure Mode: External rupture.

Prepared: A. Kay
Approved: T. Nguyen
Approval Date: 9/9/99
Change #: 2
Directive #: CCDD MECJ-01-5238

Page: 1 of 1

Phase
SMC
4.

Failure / Effect Description

LCX and hot-gas leakage into the aft compartment will cause overpressurization and fire. Loss of vehicle.

Redundancy Screens: SINGLE POINT FAILURE: N/A

Criticality
Hazard Reference
1
MF-B4S,
ME-B1A,C,
ME-B1M

~~SECRET~~
DESIGN

Component Group: Combustion Devices
CIL Item: A200-07
Part Number: RS009122
Component: Main Injector
FMEA Item: A200
Failure Mode: External rupture.

Prepared: A. Kay
Approved: T. Nguyen
Approval Date: 9/9/99
Change #: 2
Directive #: CCBD ME3-01-5238

Page: 1 of 1

Design / Document Reference

FAILURE CAUSE: A: Weld or parent material failure.

THE OXIDIZER INLET HIGH PRESSURE CAVITIES AND INLET DUCT ARE CONSTRUCTED OF INCONEL 718. THE WEIGHT SAVINGS PROVIDED BY THE HIGH STRENGTH OF INCONEL 718 IS THE PRIMARY REASON FOR ITS SELECTION. INCONEL 718 IS DUCTILE AT CRYOGENIC TEMPERATURES (1). THE ENTIRE SUBASSEMBLY RECEIVES A HEAT TREAT TO GIVE IT FULL STRENGTH (2). A FATIGUE ANALYSIS WAS PERFORMED ON THE MAIN INJECTOR. THE ANALYSIS RESULTED IN CEI REQUIREMENTS BEING MET FOR HIGH CYCLE FATIGUE AND LOW CYCLE FATIGUE (3). MAIN INJECTORS WITH CAST INLET TEES ARE LIFE LIMITED BY MAJOR WAIVER (11). FACTORS OF SAFETY FOR PRIMARY STRESS SHOW ACCEPTABLE MARGINS MEETING CEI REQUIREMENTS (4). INCONEL 718 IS OXYGEN COMPATIBLE UNDER THESE CONDITIONS (5). ALL MATERIAL IS PROCURED TO SPECIFICATION. MATERIAL. THE OXIDIZER INLET PARENT MATERIAL WAS CLEARED FOR FRACTURE MECHANICS/INDE FLAW GROWTH SINCE IT CONTAINS NO FRACTURE CRITICAL PARTS (7). THE FMEA/CIL WELDS ARE CLEARED FOR FRACTURE MECHANICS/INDE FLAW GROWTH BY THE WELD ASSESSMENT (8). TABLE A200 LISTS ALL FMEA/CIL WELDS AND IDENTIFIES THOSE WELDS IN WHICH THE CRITICAL INITIAL FLAW SIZE IS NOT DETECTABLE AND THOSE WELDS IN WHICH THE ROOT SIDE IS NOT ACCESSIBLE FOR INSPECTION. THOSE WELDS IN WHICH THE CRITICAL INITIAL FLAW SIZE IS NOT DETECTABLE ARE ACCEPTABLE FOR FLIGHT BY RISK ASSESSMENT (8). THE BRAZE JOINTS ARE DONE IN A TEMPERATURE CONTROLLED FURNACE (1). THIS REDUCES THE POTENTIAL FOR LIQUID METAL EMBRITTLEMENT OR BRAZE DEFECTS. PREVIOUS PROBLEM AREAS AT THE THRUST CONE WITH LIQUID METAL EMBRITTLEMENT HAVE INSPECTIONS TO PRECLUDE THE PROBLEM DURING FABRICATION. STRAIN GAUGE AND ACCELEROMETER DATA HAVE BEEN OBTAINED DURING TESTING IN THE AREA OF THE OXIDIZER INLET SHELLS AND INLET TEE TO DETERMINE THE ENVIRONMENT AND STRAINS IN THIS AREA. CRITICAL WELDS ARE FLUSH GROUND TO MEET CEI REQUIREMENTS (10). EVALUATION OF THE OXIDIZER MANIFOLD FROM ENGINE 2010 REVEALED NO DEFECTS OR ANOMALOUS CONDITIONS (9).

(1) RSS-8572-9; (2) RS009122; (3) RL00537, CP320R00030; (4) RSS-9546, CP320R00038; (5) RSS-8571-9; (6) R90170-163, RB0170-154, RB0170-165; (7) NASA TASK 117; (8) RSS-9758; (9) I.L. CD 89-1042; (10) ECP 967, RS009126; (11) DAR 2221

FAILURE CAUSE: B: Splitter failure.

SPLITTER VANE CRACKING IS ASSOCIATED WITH FLOW INDUCED VIBRATION. HOT FIRE TESTING IS CONDUCTED TO IDENTIFY ENGINES WHICH EXHIBIT THIS PHENOMENON (1). THESE UNITS ARE SUBJECT TO SPLITTER VANE MODIFICATION AND RE-PRESSURE TEST (2). THE PRESENT DESIGN OF THE SPLITTER VANE WAS SELECTED TO ELIMINATE THE 4kHz FLUID STRUCTURAL COUPLING MECHANISM WHICH, IN SOME CASES, HAD PREVIOUSLY RESULTED IN UNACCEPTABLY HIGH LEVELS OF VIBRATION AND EVENTUAL SPLITTER VANE CRACKING. EXTENSIVE ANALYSIS HAS BEEN PERFORMED ON THE MODIFIED SPLITTER SHOWING INFINITE LIFE AND ADEQUATE FACTORS OF SAFETY (2).

(1) RL00050-04; (2) ECP 989, R0017622

FAILURE CAUSE: ALL CAUSES

THE MAIN INJECTOR HAS COMPLETED DVS TESTING (1).

(1) DVS-333

A - 86

SSME FMEA/CIL INSPECTION AND TEST

Component Group: Combustion Devices
 CIL Item: A200-07
 Part Number: RS009122
 Component: Main Injector
 FMEA Item: A200
 Failure Mode: External rupture.

Prepared: A. Kay
 Approved: T. Nguyen
 Approval Date: 9/9/99
 Change #: 2
 Directive #: CCBD ME3-01-5239

Page: 1 of 2

A - 87

Failure Causes	Significant Characteristics	Inspection(s) / Test(s)	Document Reference
A	INLET FLANGE INLET ELBOW INLET CAP INLET CAP INJECTOR ASSEMBLY OXIDIZER SHELLS TORUS STRUCTURE BASE TEE ASILINE IGNITER ASSEMBLY MATERIAL INTEGRITY	MATERIAL INTEGRITY IS VERIFIED PER SPECIFICATION REQUIREMENTS.	RS009146 RS009147 RS009423 RS009154 RS009122 RS009235 RS009145 RS009124 RS009234 RS009179 RS009061 RB0170-153 RB0170-174 RB0170-154 RB0170-155 RB0170-213
		ASI TUBING IS INSPECTED ULTRASONICALLY AND THE O.D. IS PENETRANT INSPECTED PER SPECIFICATION REQUIREMENTS	RB0170-213
		INLET TEE, SHELLS, AND ORIFICES ARE PENETRANT INSPECTED PER SPECIFICATION REQUIREMENTS.	RA0115-116
	HEAT TREAT	HEAT TREAT IS VERIFIED PER SPECIFICATION REQUIREMENTS	RA0611-020
	WELD INTEGRITY	ALL WELDS ARE INSPECTED TO DRAWING AND SPECIFICATION REQUIREMENTS PER WELD CLASS. INSPECTIONS INCLUDE: VISUAL, DIMENSIONAL, PENETRANT, RADIOGRAPHIC, ULTRASONIC, AND FILLER MATERIAL AS APPLICABLE.	PL10011 RA0607-094 RA0115-116 RA0115-005 RA0115-127 RA0115-004
		THE OXIDIZER TORUS WELDS ARE INSPECTED PRIOR TO AND AFTER E.B. WELDING TO ASSURE CORRECT E. B. WELD TRACKING AND PENETRATION (INCLUDING BORING, ETCH, PENETRANT, AND PLUG WELDING).	RI00261
		THE WELD 55 AND 55 BRAZE JOINTS ARE INSPECTED VISUALLY, RADIOGRAPHICALLY, AND BORESCOPED PER DRAWING REQUIREMENTS. RADIOGRAPHIC INSPECTION PROVIDES 90% COVERAGE. LINE DEFECTS ARE DETECTABLE WITH 90% COVERAGE DUE TO FLAW SIZE BEING GREATER THAN 10%.	RS009126 RA0107-009 RA0115-005
		RS009061 WELD 1 IS VISUALLY INSPECTED FOR BRAZE FLOW AND LEAK CHECKED AFTER FURNACE BRAZING.	RA1507-009
		WELD 16 GEOMETRY (RADIUS BETWEEN WELD BEAD AND INLET TEE) IS VERIFIED PER DRAWING REQUIREMENTS.	RS009126 ECP 967
		OXIDIZER INLET SHELLS AND THE TORUS AREAS ARE INSPECTED FOR CORRECT CONTOUR AFTER WELDING.	RS009126

Component: Combustion Devices
 CIL Item: A200-07
 Part Number: RS009122
 Component: Main Injector
 FMEA Item: A200
 Failure Mode: External rupture.

Approved: T. Nguye
 Approval Date: 9/9/99
 Change #: 2
 Directive #: CCBDB ME3-01-5238

Page: 2 of 2

Failure Causes	Significant Characteristics	Inspection(s) / Test(s)	Document Reference	
A - CAUSES	ASSEMBLY INTEGRITY	THE OXIDIZER MANIFOLD IS PROOF PRESSURE TESTED, LEAK CHECKED, AND PENETRANT INSPECTED PRIOR TO THRUST CONE INSTALLATION PER DRAWING AND SPECIFICATION REQUIREMENTS.	RS009122 RL00127 RAC115-115	
		ASI IS PROOF PRESSURE AND LEAK TESTED PER SPECIFICATION AND DRAWING REQUIREMENTS ASI WELDS ARE PENETRANT INSPECTED AFTER PROOF TEST PER SPECIFICATION REQUIREMENTS.		
		THE HOT FIRE TESTING AND 2ND E & M INSPECTIONS VERIFY INJECTOR INTEGRITY.	RL00050-04 RL00056-06 RL00056-07	
		THE HELIUM SIGNATURE LEAK TESTING VERIFIES NO EXTERNAL LEAK OR RUPTURE	OMRSD SC0000 950	
		THE INJECTOR IS VISUALLY INSPECTED EXTERNALLY PRIOR TO EACH LAUNCH. (LAST INSPECTION)	OMRSD V41RL0.023	
	B	TEE		RSC0234
		MATERIAL INTEGRITY	MATERIAL INTEGRITY IS VERIFIED PER SPECIFICATION REQUIREMENTS	RBC170-155
			FOUR TENSILE BARS ARE FORMED WITH EACH CASTING TO ASSURE CORRECT MATERIAL TYPE AND STRENGTH.	RSC0234
			TEE AND SPLITTER ARE PENETRANT INSPECTED PER SPECIFICATION REQUIREMENTS.	RA0115-116
			SPECIAL CASTING X-RAYS ARE PERFORMED PER STANDARD AND CRITICAL GRADE REQUIREMENTS AS DETAILED ON THE DRAWING	RF0001-001 RSC0234
	TEE WITH SPLITTER IS HEAT TREATED WITH INJECTOR ASSEMBLY PER SPECIFICATION REQUIREMENTS.	RA0611-020		
ABSENCE OF HIGH VIBRATIONAL LOADING	SPLITTER VANE GEOMETRY IS VERIFIED PER CURRENT DRAWING REQUIREMENTS	RS009122 ECP 559R1		
	GIMBAL ACCELEROMETERS AND STRAIN GAUGES DETECT HIGH VIBRATIONAL LOADING DURING HOT FIRE ACCEPTANCE TESTING AND SCREEN UNACCEPTABLE UNITS OUT.	RL00050-04 RL00461		
	ENGINE GIMBAL ACCELEROMETER DATA FROM THE PRIOR FLIGHT IS REVIEWED TO DETECT HIGH VIBRATIONAL LOADS	MSFC PLN 1228		

Failure History: Comprehensive failure history data is maintained in the Problem Reporting database (PRAMS/PRACA)
 Reference: NASA letter SA21788/308 and Rockwell letter 88R00976
 Operational Use: Not Applicable.

SSME / A/CIL
WELD JOINTS

Component Group: Combustion Devices
 CIL Item: A200
 Component: RS009122
 Part Number: Main Injector
 A200

Prepared: A. Kay
 Approved: T. Nguyen
 Approval Date: 9/9/99
 Change #: 1
 Directive #: CCBD ME3-01-523A
 Page: 1 of 1

A-97

Component	Basic Part Number	Weld Number	Weld Type	Class	Root Side Not Access	Critical Initial		Comments
						Flaw Size Not	Detectable	
						HCF	LCF	
MAIN INJECTOR ASI	RSC09061	3	GTAW	I		X	X	
MAIN INJECTOR ASI	RSC09061	5	GTAW	I		X	X	
MAIN INJECTOR	RS009126	1	EBW	I				
MAIN INJECTOR	RS009126	6,7,52,53	GTAW	I	X	X	X	
MAIN INJECTOR	RS009126	8	EBW	I		X		
MAIN INJECTOR	RS009126	9	EBW	I	X			
MAIN INJECTOR	RS009126	10	EBW	II	X	X	X	
MAIN INJECTOR	RS009126	12,13	GTAW	I	X			
MAIN INJECTOR	RS009126	14,15	GTAW	I	X	X	X	
MAIN INJECTOR	RS009126	16,17	GTAW	I		X	X	
MAIN INJECTOR	RS009126	20	GTAW	I	X			
MAIN INJECTOR	RS009126	21	GTAW	II	X			
MAIN INJECTOR	RS009126	22	GTAW	I	X			
MAIN INJECTOR	RS009126	23-25,54	GTAW	I	X			
MAIN INJECTOR	RS009126	44,45	GTAW	I		X	X	
MAIN INJECTOR	RS009126	50,51	EBW	Ia	X	X	X	
MAIN INJECTOR	RS009126	59	EBW	I,b	X			
MAIN INJECTOR	RS009126	60,61	GTAW	II	X	X		
INLET SHELL	RSD08235	1 LFT	EBW	I				
INLET SHELL	RSC08235	1 RHT	EBW	I		X	X	
INLET SHELL	RSC05237	600 FLCS	FRW	I	X			

**SSME FMEA/CIL
FIELD CONFIGURATION VARIANCES FROM CIL RATIONALE**

Component Group: Combustion Devices
Item Name: Main Injector
Item Number: A200
Part Number: R5009122

Prepared: A. Kay
Approved: I. Nguyen
Approval Date: 9/8/99
Change #: 1
Directive #: CCDD ME3-01-5238

Page: 1 of 1

Base Line Rationale	Variance	Change Rationale	Variant Dash Number
1. A200-07 LOX ASI SLEEVE BRAZE IS X-RAYED AND BORESCOPEO (ECP 697)	NO BORESCOPE INSPECTION.	VISUAL VERIFICATION GAVE ADDITIONAL CONFIDENCE THAT BRAZING HAS NOT CREATED LIQUID METAL EMBRITTLEMENT. USE AS IS RATIONALE: 1. ALL SLEEVES ARE X-RAYED, WHICH SPECIFICALLY INSPECTS FOR LIQUID METAL EMBRITTLEMENT CRACKING; 2. JOINT SUSCEPTIBILITY IS LOW (NO STRAIN ON TUBE DURING WELDING, BRAZE MUST FLOW ONLY TO WITNESS HOLE).	-741, -751, -771, -761, -791, -801.
2. A200-06 WALL THICKNESS OF SECONDARY FACEPLATE RETAINERS INCREASED ON OUTER THREE ROWS. (ECP 634)	PREVIOUS CONFIGURATION HAD A THINNER WALL.	THICKER WALLS GAVE ADDITIONAL LOX POST SUPPORT IN THE HIGH FLOW AREAS. USE AS IS RATIONALE: 1. HIGH FLOW AREA POSTS WERE PLUGGED AND RODDED FOR ADDITIONAL SUPPORT; 2. LIFE LIMIT ON THE MAIN INJECTOR LOX POSTS PREVENTS DAMAGE LEVELS FROM EXCEEDING ALLOWABLE LIMITS. (DAR 1373)	-771
3. A200-06 EDDY CURRENT INSPECTION ON ALL LOX POST INERTIA WELDS. (ECP 342)	NO EDDY CURRENT INSPECTION OF INERTIA WELDS.	EDDY CURRENT INSPECTION PROVIDE ADDITIONAL CONFIDENCE IN INTERNAL WELD INTEGRITY. USE AS IS RATIONALE: 1. INERTIA WELDS ARE CONTROLLED BY SPECIFICATION; 2. NO FAILURE HISTORY WITH HAYNES 188 POSTS; 3. SURFACE FINISH IS CONTROLLED TO REDUCE STRESS CONCENTRATIONS; 4. ROW 13 POSTS ARE DYE PENETRANT INSPECTED ON O.D	-791, -751, -771, -781, -791, -801, -811, -851.
4. A200-07 ELIMINATION OF BRAZE JOINTS OF ASI INLET TUBE TO BIFED TIRES	BRAZED PREVIOUS CONFIGURATION	ELIMINATION OF BRAZE JOINT ELIMINATES THE POSSIBILITY OF LIQUID METAL EMBRITTLEMENT. USE AS IS RATIONALE: 1. BRAZE JOINTS ARE DONE WITHOUT INDUCED LOADS 2. NO RESIDUAL STRESSES IN TUBES. 3. SECTIONED HARDWARE SHOWS NO PROBLEMS	-741, -771, -781.
5. A200-07 SPLITTER VANE GEOMETRY IS VERIFIED PER CURRENT DRAWING REQUIREMENTS. (ECP 989R1)	SPLITTER VANE GEOMETRY DOES NOT MEET CURRENT DRAWING REQUIREMENTS.	RE-DESIGN OF THE SPLITTER VANE ALTERED THE STRUCTURAL RESPONSE OF THE VANES TO FLOW, ELIMINATING FLOW INDUCED CRACKING. USE AS IS RATIONALE: 1. ENGINES NOT MEETING CURRENT SPLITTER VANE DRAWING REQUIREMENTS ARE SCREENED AT GREEN RUN TO IDENTIFY THOSE EXHIBITING THE 4 KHz RESPONSE. THESE ENGINES ARE REWORKED TO CURRENT DRAWING REQUIREMENTS. RE-PRESSURE TESTED AND RE-IDENTIFIED.	-1021, -1141, -1161, -1171, -1201, -1301, -1311, -1321, -1361, -1441

A-98