

SSME EA/CIL  
**REDUNDANCY SCREEN**

Component Group: Pneumatic Controls  
 CIL Item: C300-07  
 Component: Helium Precharge Valve  
 Part Number: RS010180  
 Failure Mode: Failure to contain oxidizer.

Prepared: P. Lowrimore  
 Approved: T. Nguyen  
 Approval Date: 6/2/99  
 Change #: 1  
 Directive #: CCBD ME3-01-5213  
 Page: 1 of 1

Phase	Failure / Effect Description	Criticality Hazard Reference
PSMCS 4.1	Failure of check valve body provides a flow path for LOX/GOX into orbiter aft bay causing overpressurization of aft bay. Loss of vehicle.  Redundancy Screens: SINGLE POINT FAILURE: N/A	1 ME-C3P, ME-C3S, ME-C3M, ME-C3C, ME-C3D, ME-C3A

**SSME FMEA/CIL**  
**DESIGN**

Component Group: Pneumatic Controls  
CIL Item: C300-07  
Component: Helium Precharge Valve  
Part Number: RS010180  
Failure Mode: Failure to contain oxidizer.

Prepared: P. Lowrimore  
Approved: T. Nguyen  
Approval Date: 8/2/99  
Change #: 1  
Directive #: CCBDMES-01-5213  
Page: 1 of 1

---

Design / Document Reference

---

**FAILURE CAUSE: ALL CAUSES**

INCONEL 718 IS USED TO MANUFACTURE THE CHECK VALVE HOUSING (1). IT HAS HIGH STRENGTH AND DUCTILITY (2). IT IS CORROSION RESISTANT AND EXHIBITS HIGH STRESS CORROSION CRACKING RESISTANCE (3). INCONEL 718 HAS A HIGH MODULUS OF ELASTICITY (1). THE ASSEMBLY HAS COMPLETED DESIGN VERIFICATION TESTING (4), INCLUDING VIBRATION AND ENDURANCE TESTING (5). HIGH CYCLE AND LOW CYCLE FATIGUE LIFE, AS WELL AS THE MINIMUM FACTORS OF SAFETY FOR THE HELIUM PRECHARGE VALVE, MEET DEI REQUIREMENTS (6), EXCEPT FOR PROOF PRESSURE FACTOR WHICH IS ACCEPTED PER MAJOR WAIVER (7). THE HPV WAS CLEARED FOR FRACTURE MECHANICS/INDE FLAW GROWTH, SINCE IT CONTAINS NO FRACTURE CRITICAL PARTS (8). AN EXAMINATION OF ENGINE 2010 HPV SHOWED NO EVIDENCE OF HPV CHECK VALVE HOUSING FAILURE. THE VALVE ACCUMULATED OVER 13,300 SECONDS AND 43 STARTS.

(1) RSC10182; (2) RSS-8582-5; (3) MSFC-SPEC-522; (4) DVS-SSME-517; (5) RSS-517-53, RSS-517-51. (6) RL00532, CP370R0003B, RSS-8546; (7) DAR 2233; (8) NASA TASK 117

SSME Fiv. CIL  
**INSPECTION AND TEST**

Component Group: Pneumatic Controls  
 CIL Item: C300-07  
 Component: Helium Precharge Valve  
 Part Number: RS010180  
 Failure Mode: Failure to contain oxidizer.

Prepared: P. Lowrimore  
 Approved: T. Nguyen  
 Approval Date: 6/2/89  
 Change #: 1  
 Directive #: CCB0 ME3-01-5213  
 Page: 1 of 1

Failure Causes	Significant Characteristics	Inspection(s) / Test(s)	Document Reference
ALL CAUSES	HOUSING, CHECK VALVE HELIUM PRECHARGE VALVE		RS010182
	MATERIAL INTEGRITY	MATERIAL INTEGRITY IS VERIFIED PER DRAWING REQUIREMENTS. THE HEAT TREAT IS VERIFIED PER DRAWING AND SPECIFICATION REQUIREMENTS.	RS010182 RA0611-020
	PROOF TESTING	THE HOUSING IS PENETRANT INSPECTED AFTER FINISH MACHINING AND HEAT TREATMENT. THE HPV ASSEMBLY IS PROOF TESTED, OUTLETS AND TOTAL ASSEMBLY.	RA0115-115 RS010180 RS010182 RL00459
	PRE-FLIGHT CHECKOUT	CHECK VALVE LEAK TEST IS PERFORMED AFTER 10 STARTS. FLIGHT READINESS TEST, INCLUDING PNEUMATIC SHUTDOWN, IS PERFORMED EACH FLIGHT. FLIGHT READINESS TESTS AND VALVE CYCLE VERIFICATION ARE PERFORMED EACH FLIGHT. PNEUMATIC SYSTEM CHECKOUT IS PERFORMED EACH FLIGHT. A HELIUM SIGNATURE LEAK TEST IS PERFORMED PRIOR TO EACH FLIGHT. AFT CLOSEOUT INSPECTION IS PERFORMED PRIOR TO FLIGHT. (LAST TEST)	OMRSD V41B00.100 OMRSD V41AS0.030 OMRSD S00FA0.211 OMRSD V41ASC.030 OMRSD S00FA0.213 OMRSD V41ASC.020 OMRSD S00000.950 OMRSD V41BU0.070

C-83

Failure History: Comprehensive failure history data is maintained in the Problem Reporting database (PRAMS/PRAGA).  
 Reference: NASA letter SA21/88/308 and Rocketdyne letter 80RC09761.  
 Operational Use: Not Applicable.