CIL

EMU CRITICAL ITEMS LIST

## 5/30/2002 SUPERSEDES 12/31/2001

Page 1

Date: 3/27/2002

\_ \_\_ \_\_ \_\_ \_\_

NAME		FAILURE				
P/N QTY	CRIT	MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE		
		104FM36				
PRESSURE BOOT ASSEMBLY, ITEM 104 (1) LEFT (1) RIGHT	3/2RB	Loss of heel screw.	END ITEM: Loss of one of nine screws.	A. Design - The heel assembly of the Enhanced Boot is constructed from 7075-T73 aluminum and covered with peroxide catalyzed silicone rubber.		
0104-210895- 25/26/29/30; 0104-210895- 33/34/35/36 (2)		Defective Material; Heel, helicoils, loose screw.	GFE INTERFACE: Unable to engage foot restraint with loss of four consecutive screws.	The heel top attachment screws are fabricated from A-286 stainless steel and are procured to MS or NAS specifications. Loss of the heel top attachment screws is precluded in design by adherence to standard engineering torque requirements for screw installation. Design requirements for proper installation of helicoils are specified in the assembly procedures when the helicoils are installed in the heel.		
				B. Test -		
			MISSION:	Acceptance:		
			Terminate EVA with loss of	Components - see inspection.		
			four	PDA:		
			consecutive screws.	The following test is conducted at the LTA assembly level in accordance with ILC Document 0111-70028J.		
			CREW/VEHICLE:	Proof pressure test at $8.0 + 0.2 - 0.0$ psig for a minimum of 5 minutes conduct with the TMG removed.		
None. Certification: (P/N 0104-89652				Certification: (P/N 0104-89652):		
			TIME TO EFFECT /ACTIONS: Minutes.	The Enhanced Boot heel and heel top bracket were successfully tested (manned) during certification to duplicate operational life. The test subject successfully performed 400 portable foot Restraint engagement/disengagement cycles. (Ref. ILC Doc. 0111-711330). The following usage, reflecting requirements of significance to the boot, was documented during certification:		
			TIME AVAILABLE: N/A			
			TIME REQUIRED:			
			N/A	Requirement S/AD Actual		
			REDUNDANCY SCREENS: A-PASS B-FAIL C-PASS	Pressurized Hours         458         916           Pressurized Cycles         300         300           Ankle Cycles         11614         24000           Total Steps         38800         77760		
				The Enhanced Boot heel and heel top bracket were successfully subjected to a BTA ultimate pressure of 13.2 psig. (1.5 times max BTA operating pressure based on 8.3 psig). (Ref. ILC Doc. 0111-711330).		
				C. Inspection - Components and material manufactured to ILC requirements at an approved supplier are documented from procurement through shipping by the supplier. ILC incoming receiving inspection verifies that the materials received are as identified in the procurement documents, that no damage has occurred during shipment and that supplier certifications have been received which provide traceability information.		
				The following MIP's are performed during the pressure boot assembly		

CIL EMU CRITICAL ITEMS LIST			5/30/2002 SU	UPERSEDES 12/31/2001	Page 2 Date: 3/27/2002
NAME P/N QTY	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE	
· – – – –		104FM36			
				manufacturing process to assure that the failure causes fabricated item:	are precluded from the
				<ol> <li>Helicoil installation is verified during assembly.</li> <li>Verification of the presence of screws during the bo bracket screw torquing.</li> </ol>	oot heel and heel top
				During PDA, the following inspection points are performe level in accordance with ILC Document 0111-70028J:	ed at the LTA assembly
				<ol> <li>Visual inspection for material degradation.</li> <li>Visual inspection for structural damage following pr the TMGs removed.</li> </ol>	roof pressure test with
				D. Failure History - None.	
				E. Ground Turnaround - None.	
				F. Operational Use - 1. Crew Response	
				Pre/post-EVA : Troubleshoot problem, if no success, cont without foot restraint.	tinue EVA operations
				EVA : Troubleshoot problems, if no success, continue EVA or use foot restraint toe bar for immobilization of affe	
				2. Special Training	
				No training specifically covers this failure mode.	
				3. Operational Considerations	
				Use of foot restraint not required.	
				Use of foot restraint not required.	

## EXTRAVEHICULAR MOBILITY UNIT

## SYSTEMS SAFETY REVIEW PANEL REVIEW

FOR THE

I-104 LOWER TORSO ASSEMBLY (LTA)

CRITICAL ITEM LIST (CIL)

EMU CONTRACT NO. NAS 9-97150

Approved by: WASA - SSA

M. Snyler HS - Reliability

<u>R. Munford</u> 4/24/02 HS - Engineering Manager

5/2/02 12 N/AS/ACCERT

5.29.02

h 5-30-02

6/04/02 ASAU CTOW

1/3/02 ASAM Program Manager