CIL

EMU CRITICAL ITEMS LIST

5/30/2002 SUPERSEDES 12/31/2001

Page 1

Date: 4/24/2002

NAME		FAILURE		
P/N QTY	CRIT	MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
		106FM10Y		
DUAL SEAL WRIST BEARING, GLOVE SIDE, ITEM 106 (1) LEFT (1) RIGHT	3/1RA	External gas leakage (ball port or test port).	END ITEM: Gas leakage through test port or ball port seal.	A. Design - The fluorosilicone O-seals mounted in the test port or ball port plug are in a static condition. Proper lead-in chamfers and radii on mating hardware components preclude damage to the O-seals during installation.
(1) LEFT (1) RIGHT 10088-02 (2)		port). Contamination, wear or deterioration of ball port plug or test port plug O- seal. Defective material; ball port or test port plug O- seal.	<pre>port or ball port seal. GFE INTERFACE: Opening of leakage path between ball race area and ambient. MISSION: No effect with single failure (loss of test port or ball port seal). With second failure (loss of primary seal) high O2 use. Abort EVA. CREW/VEHICLE: No effect with single failure (test port or ball port seal) or second failure (primary seal). Loss</pre>	<pre>components preclude damage to the O-seals during installation. The screws are fabricated from an AMS 5737 (A286) stainless steel and procured to A.N. specifications. Loss of the screws is precluded in design by adherence to standard engineering torque requirements for screw installations. B. Test - Component Acceptance Test: The wrist bearing is subjected to testing per Airlock ATP 10088 at Airlock with ILC source verification. During acceptance testing, a test port with the same size O-ring is utilized for pressure testing. No specific pressure test is conducted on the test port plug assembly. Certification: The dual seal wrist bearing successfully tested (manned) during SSA certification testing to duplicate operational usage (Ref. ILC Report 0111- 711330). The following usage reflecting requirements of significance to the wrist bearing was documented during certification: Requirement S/AD Actual </pre>
			with third failure (loss of SOP). TIME TO EFFECT	The following MIP's are performed during the wrist bearing assembly manufacturing process to assure the failure cause is precluded from the fabricated item:
			/ACTIONS: Seconds.	 Verification of presence of ball port plug, test port plug and retainer screws.
			TIME AVAILABLE: Minutes.	2. Visual inspection of ball port and test port plug O-seal for gouges, nicks, tears and mold imperfections.
			TIME REQUIRED: Immediate.	During PDA, the following inspection points are performed at the glove assembly level in accordance with ILC Document 0111-70028 (4000 glove) or 0111-710112 (Phase VI glove):
			REDUNDANCY SCREENS: A-FAIL	 Inspection for cleanliness to VC level. Visual inspection for damage after proof-pressure test.

CIL

EMU CRITICAL ITEMS LIST

5/30/2002 SUPERSEDES 12/31/2001

Page 2

Date: 4/24/2002

				Date: 4/24/2002
NAME P/N QTY	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
		106FM10Y		
			B-N/A C-PASS	D. Failure History - None.
				E. Ground Turnaround - None, however, every 4 years or 229 hours of manned pressurized time, the wrist bearing assembly is disassembled, cleaned, inspected, lubricated and reassembled.
				F. Operational Use - Crew Response - PreEVA: No response, single failure not detectable. EVA: No response, single failure not detectable.
				Special Training - No training covers this failure mode.
				Operational Considerations - Flight rule A15.1.2-2 of "Space Shuttle Operational Flight Rules", NSTS-12820 defines go/no go criteria related to EMU pressure integrity. Generic EVA Checklist, JSC-48023, procedures Section 3 (EMU Checkout) and 4 (EVA prep) verify hardware integrity and systems operational status prior to EVA. Real Time Data System allows ground monitoring of EMU systems.

EXTRAVEHICULAR MOBILITY UNIT

SYSTEMS SAFETY REVIEW PANEL REVIEW

FOR THE

I-106 GLOVE ASSEMBLY

CRITICAL ITEM LIST (CIL)

EMU CONTRACT NO. NAS 9-97150

Prepared by: __________ Project Engineering

Approved by:

<u>M. Snydin</u> HS - Reliability

R. Munford 4/24/02 HS - Engineering Manager

Janw 5/23/02

Che Jon 6/3/02

6/05/02 ASA CION -

:/3/02 Riceran