

CRITICAL ITEMS LIST
FILE: CRL-#155/2

NAME P/N QTY	UNIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
FAH/SEPAR- ATOR/ PUMP/MOTOR ASSEMBLY ITEM 125 SN787494-0 (1) FC67-1 0	2/1R	123FH031 EXTERNAL GAS LEAKAGE, VENTILATION CIRCUIT, CAUSE: SEAL FAILURE.	END ITEM: SALE GAS LEAKAGE TO AMBIENT. OFF INTERFACE: EXCESSIVE CONSUMPTION OF THE PRIMARY OXYGEN SUPPLY. THE SOP IS AUTOMATICALLY ACTIVATED DURING EVA IF THE SAIT PRESSURE DROPS TO 1.55 PSID. MISSION: TERMINATE EVA. LOSS OF USE OF ONE CML. CREW/VEHICLE: NONE FOR SINGLE FAILURE, POSSIBLE LOSS OF CREWMAN WITH LOSS OF SOP.	B. DESIGN - THE UNIT HAS FIVE EXTERNAL LEAKAGE PATHS THROUGH RADIAL "O" RING SEALS OF SILICONE, 1 FLUOROSILICONE, 5 VITONS AND A LEAKAGE PATH THROUGH A FACE TYPE, O-RING SEAL (VITON) CONFIGURATION DIMENSIONS AND RIGIDNESS OF ASSEMBLY PROVIDE SQUEEZE UNDER ALL OPERATING CONDITIONS. OPERATING FLUID TEMPERATURE AND PRESSURE IS NOT EXTREME. VENT LOOP GAS IS AT 4.5 PSID. B. TEST - RECERTIFICATION TEST - THE ITEM COMPLETED 10,000 HOURS OF OPERATION AND 8400 ON/OFF CYCLES EXCEEDING THE 15 YEAR CERTIFICATION REQUIREMENT BY MORE THAN A FACTOR OF THREE. THE 15 YEAR STRUCTURAL VIBRATION, ELECTRICAL VIBRATION, ELECTRICAL VIBRATION AND DESIGN SHOCK WAS COMPLETED 12/84. THE FOLLOWING ENGINEERING CHANGES HAVE BEEN INCORPORATED AND CERTIFIED SINCE THIS CONFIGURATION WAS CERTIFIED: 42004-342-35 (CHANGE POWER CONSUMPTION REQUIREMENT - MORE AMP), 42006-404 (INCORPORATE MITRAC AS RETAINING NUT), 42006-424 (SEAL CUP CHANGE TO ASSURE A GOOD WELD), 42006-810 (MATER PUMP CHANGES NOT SUSCEPTIBLE TO CONTAMINATION, NONE BREAK EDGES AND DEBRISING OPERATIONS 42006-934 (CHANGE BEARING LIMITED LIFE REQUIREMENTS). COMPONENT ACCEPTANCE TESTS - THE VENT CIRCUIT IS REVERSE PUMP PRESSURE TESTED, BY EVACUATING IT TO 0.2 PSIA MAX IN SEA LEVEL AMBIENT CONDITIONS (P + 14.5 INHG), FOR 5 MINUTES. THE VENT CONDUIT IS THEN PRESSURIZED TO 25.7-25.7 PSIA FOR 5 MINS. SEQUENTIALLY THE ITEM IS HELIUM LEAKAGE TESTED BY PRESSURIZING THE ITEM (VENT CIRCUIT) TO 6.0-8.0 PSIA ONE IN CHAMBER VACUUM. THE LEAKAGE MUST NOT EXCEED 4.5 X 10 ⁻² SCC/SEC. HE. SEE POA TESTING PER SEMI-40-010 - THE ITEM (P155) VENT CIRCUIT IS PRESSURIZED TO 0.15-0.45 PSID FOR 5 MINUTES. SEQUENTIALLY A SYSTEM EXTERNAL LEAKAGE TEST IS PERFORMED. THE VENT CIRCUIT IS PRESSURIZED TO 10.9-11.0 PSIA. LEAKAGE MUST NOT EXCEED 4.44 SCC/WH 02.

CEL
 CRITICAL ITEMS LIST
 FILE: CIL-PLSS/2

NAME P/N QTY	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
IAN/SEPAR- ATOR/ PUMP/MOTOR ASSEMBLY ITEM 323 SV787446-0 111 7C67-2 8	E/IR	123FM03; EXTERNAL GAS BEARING, VENTILATION CIRCUIT.		E. INSPECTION - THE BEARING CARRIER O-SEAL GROOVE IS 100% INSPECTED FOR DIMENSIONAL AND SURFACE FINISH REQUIREMENTS AFTER MACHINING. THE STATOR SLEEVE ID WHICH MATES UP WITH BEARING CARRIER O-SEAL IS 100% INSPECTED FOR SURFACE FINISH REQUIREMENTS AFTER MACHINING. THE MOTOR HOUSING ID WHICH MATES UP WITH THE STATOR SLEEVE'S O-SEAL IS 100% INSPECTED FOR SURFACE FINISH REQUIREMENTS AT RECEIVING INSPECTION. THE MOTOR HOUSING ID WHICH MATES UP WITH THE STATOR SLEEVE'S O-SEAL IS 100% INSPECTED FOR SURFACE FINISH REQUIREMENTS AFTER MACHINING AND REWORKING TO ACCEPT THE STATOR SLEEVE FOR TANGED MOTOR RETROFITS. VOLUTE HOUSING BORE WHICH MATES TO MOTOR HOUSING O-SEAL IS INSPECTED FOR DIAMETER AND SURFACE FINISH. MOTOR HOUSING TO VOLUTE HOUSING O-SEAL GROOVE IS 100% INSPECTED FOR DIMENSIONS AND SURFACE FINISH. VOLUTE HOUSING FACE SEAL O-SEAL GROOVE FINISH MATE WITH VALVE (MODULE) IS 100% INSPECTED FOR DIMENSIONS AND SURFACE FINISH. VALVE MIDDLE BORE FOR ITEM 115 MOTOR IS 100% INSPECTED FOR BOTH BORE ID AND FACE SEAL SURFACE FINISH. ALL O-SEALS ARE INSPECTED FOR SURFACE CHARACTERISTICS PER SYMS432, 100% FOR CLASS I AND II O-SEALS, AND AT LEAST 2,5 AND FOR CLASS III. O-SEAL ON VOLUTE TO MOTOR HOUSING INTERFACE IS ASSEMBLED WITH BRAYCOTE LUBRICANT WITH AN OPERATION SHEET NOTE STATING "HANDLE PREFORMED PACKING O-SEALS WITH CARE. DO NOT OVERSTRETCH. NICK OR CUT DURING ASSEMBLY".

CIL
 CRITICAL ITEMS LIST
 FILE: CIL-PLSS/2

NAME P/N QTY	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	WATERMARK FOR ACCEPTANCE
FAN/SEPAR- ATOR/ PUMP/MOTOR ASSEMBLY ITEM 123 SV787894-B 411	R/10	RESPONSE; EXTERNAL LEAKAGE, VENTILATION CIRCUIT.		<p>C. INSPECTION - (CONTINUED)</p> <p>SV747776 MOTOR HOUSING - THE MOTOR HOUSING TO WHICH MATE WITH THE STATOR SLEEVE'S O-SEAL IS 100% INSPECTED FOR SURFACE FINISH REQUIREMENTS AT RECEIVING INSPECTION.</p> <p>SV707967-100 MOTOR HOUSING - THE MOTOR HOUSING TO WHICH MATE WITH THE STATOR SLEEVE'S O-SEAL IS 100% INSPECTED FOR SURFACE FINISH REQUIREMENTS AFTER MOUNTING AND REMOVING TO ACCEPT THE STATOR SLEEVE FOR CARRIED MOTOR RETROFITS.</p> <p>MISCELLANEOUS - VALVE HOUSING BORE WHICH MATE TO MOTOR HOUSING O-SEAL IS INSPECTED FOR DIAMETER AND SURFACE FINISH. MOTOR HOUSING TO VALVE HOUSING O-SEAL GROOVE IS 100% INSPECTED FOR DIMENSIONS AND SURFACE FINISH. VALVE HOUSING FACE SEAL O-SEAL GROOVE WHICH MATE WITH VALVE NOZZLE IS 100% INSPECTED FOR DIMENSIONS AND SURFACE FINISH. VALVE NOZZLE BORE FOR ITEM 123 MOTOR IS 100% INSPECTED FOR BOTH DEPTH AND FACE SEAL SURFACE FINISH. ALL O-SEALS ARE INSPECTED FOR SURFACE CHARACTERISTICS PER SWS3432, 100% FOR CLASS I AND II O-SEALS, AND AT LEAST 1.5 AQL AND 2.5 AQL FOR CLASS III AND IV O-SEALS RESPECTIVELY. O-SEAL ON VALVE TO MOTOR HOUSING INTERFACE IS ASSEMBLED WITH BRAYCOTE LUBRICANT WITH AN OPERATION SHEET NOTE STATING "HANDLE PREFORMED PACKING TO SEAL WITH CARE, DO NOT OVERSTRETCH, HIGH OR CUT DURING ASSEMBLY."</p>
EC67-B 4				

C24
CRITICAL ITEMS LIST
FILE: CIL-PL58/2

8/5/88 SUPERSEDES 4/4/88

NAME P/N QTY	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
FAN/SEPAR- ATOR/ PUMP/MOTOR ASSEMBLY ITEM 123 SV78994-B (1)	2/10	TESTING; EXTERNAL LEAKAGE, VENTILATION CRACKED.		<p>D. FAILURE HISTORY - N-211-100-2907 (7-25-88) GAS LEAK AT TRANSFER TIME BETWEEN THE BUFFER AND THE FAN/PUMP/ SEPARATOR OULET CAUSED BY BRUACED O-SEAL DURING ASSEMBLY. A CAUTION NOTE WAS ADDED TO THE OPERATION SHEETS TO ENSURE THE ALIGNMENT OF THE TRANSFER TUBE PRIOR TO AND DURING INSTALLATION OF THE FAN/PUMP/SEPARATOR. REVISION A OF OPERATION SHEET SV78928-11-02, OP 60 INCORPORATED THIS NOTE. YELLOW TAG NOTICE 1078 ISSUED TO THE FIELD TO ENSURE FIELD CONCURRENCE.</p> <p>* N-211-123-20115-5-089 GAS LEAK AT VOLUTE HOUSING AND MOTOR HOUSING INTERFACE CAUSED BY RAISED MATERIAL IN THE O-SEAL GROOVE. RAISED MATERIAL WAS CAUSED BY A MACHINING PROCESS DURING REPROFIT TO "CAMMED" MOTOR CONFIGURATION. CORRECTIVE ACTION: OP SHEETS WERE REVISED AND A FEATURE WAS INCORPORATED TO PROTECT O-SEAL GROOVE SURFACE.</p> <p>E. GROUND TURBULENCE - TESTED PER SV789-R-088 GAS STRUCTURAL AND LEAKAGE.</p> <p>F. OPERATIONAL USE - CREW RESPONSE PREVA: WHEN DETECTED PRIOR TO PRIMARY O2 TANK TOPOFF, TROUBLE SHOOT PROBLEM, IF NO SUCCESS, CONSIDER EIM 3 IF AVAILABLE. EIM 30 GO FOR EVA. EVA: WHEN EIM DATA CONFIRMS AN ACCELERATED PRIMARY O2 USE RATE, TERMINATE EVA. TRAINING - STANDARD EMI TRAINING COVERS THIS FAILURE MODE. OPERATIONAL CONSIDERATIONS - FLIGHT RULES BEFORE REQUIRE EVA TERMINATION WHEN NONHEAT PRIMARY CONSUMABLES REMAIN. EVA CHECKLIST PROCEDURES VERIFY BARRIERS INTEGRITY AND SYSTEMS OPERATION STATUS PRIOR TO EVA. REAL TIME DATA SYSTEM ALLOWS GROUND MONITORING OF EMI SYSTEMS.</p>
FC63-4 0				