CIL

EMU CRITICAL ITEMS LIST

\_\_\_\_\_\_

## 5/30/2002 SUPERSEDES 12/31/2001

- -- -- -- -- -- -- -- --

\_ \_\_ \_\_ \_\_ \_\_ \_\_ \_\_ \_\_ \_\_

Page 1

Date: 3/27/2002

\_\_\_\_\_

NAME		FAILURE		
P/N		MODE &		
QTY	CRIT	CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
		134FM02		
RELIEF VALVE, CONDENSATE WATER, ITEM 134	2/1R	Fails closed.	END ITEM: Unable to deliver	A. Design - Teflon coating the valve seat minimizes stiction force on the elastameric silicone diaphragm. The seat compression is controlled by a metal to metal stop.
SV769403-6 (1)		Diaphragm sticks to seat, plunger	separator water to the reservoir.	The plunger and bore are terion coated to reduce friction.
		jams, filter clogs.		B. Test - Component Acceptance Test -
			Water	test the valve must crack at 2.5-3.2 psid. Crack is defined as a minimum flow through the valve of 1 cc/min During the performance test the valve must flow
			ducted to the	13.2-14.2 lbs/hr water at a pressure differential of 3.2-3.5 psid.
			MISSION:	During fan pump testing per SEMU-60-010 it is verified that the condensate water relief valve will maintain a differential pressure of 3.1-2.7 psid between the
			Possible	separator outlet and the feedwater circuit.
			neimet logging.	Certifiction Test - Certified for a useful life of 20 years (ref. EMUM-1430).
			None for	C Inspection -
			single	The diaphragm sealing surface that opens and closes flow to the value seat
			failure. Possible loss of crewman	orifice is 100% inspected to meet dimensional requirements as well as being visually inspected at 10x magnification for any surface defects. The valve seat is 100% inspected for being properly teflon coated.
			with loss of SOP.	The interfacing surfaces between the plunger and the valve housing are 100%
			TIME TO EFFECT /ACTIONS:	inspected to meet dimensional and surface finish requirements, as well as for being properly teflon coating.
			Minutes.	D. Failure History - H-EMU-100-A009 (7-13-84) The Delta P across the 134 valve was higher than
			TIME AVAILABLE: Minutes.	specification. The out of spec. measurement was produced by measuring psid with an absolute pressure transducer. Corrective action: A differential pressure transducer will replace the absolute for PDA testing.
			TIME REQUIRED: Seconds.	J-EMU-134001 (10/14/94) The 134 Water Relief Valve S/N 027 failed closed due
			REDUNDANCY	carryover into the vent loop. The filter contamination was identified as silicone grease and polyester fabrics from unknown sources. No corrective
			SCREENS: A-PASS	action taken.
			B-PASS C-PASS	B-EMU-134-A001 (5/4/95) - Water carryover in the vent loop caused by clogged Item 134 valve filter and gasket (shim) deforming and blocking the inlet. The filter was clogged with braycote grease (from o-rings) and fibers from vent loop. Filters will be replaced every 2 years and gasket will be redesigned to
				E. Ground lurnaround - Tested for non-EET processing per FEMU-R-001, Fan/Pump/Separator/Vent Flow Sensor Performance. FEMU-R-001 Para 8.2 EMU Preflight KSC Checkout for EET processing.

CIL EMU CRITICAL ITEMS LIST			5/30/2002 SUPERSEDES 12/31/2001		Page 2 Date: 3/27/2002
NAME P/N QTY	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE	
		134FM02			
				F. Operational Use - Crew Response - PreEVA: Trouble shoot problem, if no success, consider EMU go for SCU without fan. PostEVA: Open helmet purge valve until helmet can be doffed EVA: If helmet fogging occurs or significant amounts of wat helmet vent duct, terminate EVA. Open helmet purge valve. Training - No training specifically covers this failure mod Operational Considerations - Flight rules define EMU go to remain on SCU (available for EVA checklist procedures verify hardware integrity and syst status prior to EVA. Real Time Data System allows ground mo systems.	3 if available. EMU er detected exiting e. rescue if required). ems operational nitoring of EMU

EXTRAVEHICULAR MOBILITY UNIT

SYSTEMS SAFETY REVIEW PANEL REVIEW

FOR THE

I-134 CONDENSATE WATER RELIEF VALVE

CRITICAL ITEM LIST (CIL)

EMU CONTRACT NO. NAS 9-97150

Prepared by: HS - Project Engineering Approved by: TMB

M. Smyle HS - Reliability

<u>Ula Playet</u> HS - Engineering Manager RMu

235

MOD

MASAL Crew

ratir Manager