CIL

EMU CRITICAL ITEMS LIST

5/30/2002 SUPERSEDES 12/31/2001

Page 1

Date: 3/27/2002

NAME		FAILURE		
?/N		MODE &		
PTΥ	CRIT	CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
		135FM01A	· – – – – – – ·	
EEDWATER RELIEF	2/1R	Internal water	END ITEM:	A. Design -
LVE, ITEM 135		leakage, fails	Water leakage	A 38 micron inlet filter and 140 micron outlet filter protect the valve details
		open.	to ambient.	from contamination. The spring is stressed conservatively in this small stroke
V769404-7				application. The plunger and bore are teflon coated to reduce friction. The beau
(1)		Seat	GFE INTERFACE:	seal on the elastameric diaphragm circumference provides seal squeeze under all loading conditions.
		contamination,	Depletion of	The valve diaphragm is designed to minimize membrane stresses by limiting the
		spring fracture,	the water reservoir.	stroke to 0.020 inches max. and utilizing a teflon coated piston for support.
		diaphragm	Loss of	
		leakage,	cooling and	B. Test -
		plunger fails	defog.	Component Acceptance Test -
		to close.		An internal leakage test is run per AT-E-135 using one of two methods. In the
		Housing seal bypass leakage.	MISSION:	first method, the relief valve is pressurized to 15.5–16.5 psig with nitrogen. No bubbles are allowed from the outlet for a 5 minute minimum test period. If
		Sypubb reakage.	Terminate EVA	this test is not passed, the relief valve is then pressurized to 16.0-17.0 psig
			when the water	with water for 60 minutes minimum. The water leakage is not to exceed 0.01 cc/h
			supply drops	A performance test is run in which the relief valve must have a cracking
			below CWS limits.	pressure of 18.0-20.0 psid. Cracking pressure is defined as water just starts t
			limits.	flow through the valve. The valve must also reseat at 18.0-20.0 psid. In addition with the valve pressurized to 20.0-20.2 psid it must flow 0.9-22.7
				cc/min of water.
			CREW/VEHICLE:	All rig lines and test fixtures are cleaned to HS3150 EM150 to prevent them from
			None for	contaminating the item.
			single failure.	PDA Test -
			Possible loss	During testing per SEMU-60-010 the relief valve must have a cracking pressure
			of crewman	and a reseat pressure of 18.0-20.0 psig.
			with loss of	
			SOP.	Certification Test -
				Certified for a useful life of 20 years (ref. EMUM-1079).
			TIME TO EFFECT	C. Inspection -
			/ACTIONS: Minutes. If	A cleanliness level of HS3150 EM150 is maintained during the assembly and
			there is	testing of the valve. This level requires a mandatory inspection for verification.
			insufficient	The 140 micron screen is 100% inspected for being properly resistance welded an
			water to	bonded to the valve housing as well as visually for defects. The 38 micron
			provide	screen is 100% inspected for being properly bonded to the valve seat as well as
			cooling/	visually for defects. The spring is 100% inspected to meet dimensional and force displacement
			defog, open purge valve to	requirements.
			activate the	The sealing interfaces between the valve housing and the valve body are 100%
			SOP.	inspected to meet dimensional and suface finish requiremnts.
				The diaphragm is 100% inspected to meet dimensional and surface finish
			TIME	requirements, along with being visually inspected for defects. The diaphragm surface that opens and closes flow to the valve seat orifice is inspected under
			AVAILABLE: Minutes.	10x magnification for any surface defects.
				An inprocess test is run to check for internal leakage around the diaphragm. No
				leakage is allowed.
			TIME REQUIRED:	
			Seconds.	The interfacing surfaces between the valve plunger and housing are 100% inspected to meet dimensional and surface finish rquirements, as well as for
				Inspected to meet dimensional and surface linish routrements, as Well as Tor

EMU CRITICAL ITEMS LIST

5/30/2002 SUPERSEDES 12/31/2001

Page 2

Date: 3/27/2002

NAME		FAILURE		
P/N QTY	CRIT	MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
		135FM01A		
		ISSIMULA	REDUNDANCY SCREENS: A-PASS B-PASS C-PASS	being properly teflon coated. The interfacing surfaces between the valve module housing and the valve housing are 100% inspected to meet dimensional and surface finish requirements. The O-seals are inspected for surface characteristics per SVHS3431; 100% for Classes I and II, at least 1.5 AQL for Class III. An inprocess test is run to check for housing seal bypass leakage. No leakage is allowed.
				D. Failure History - H-EMU-135-A001 (8-12-81) The 135 valve failed internal leakage during acceptance test due to aluminum oxide contamination drying on the diaphragm and valve seat after the valve was removed from the system. Corrective action: A procedure has been instituted that requires flush cleaning and vacuum drying of any valve removed from the system.
				H-EMU-135-D002 (4-14-83) Internal seat leakage due to an improper test fixture. Corrective action: The test fixture was revised.
				H-EMU-135-D004 (9-27-83) The 135 valve experienced an excessive leakage rate during component acceptance testing. Inspection of the valve diaphragm (P/N SV767683-2) revealed a defect of the sealing surface. Corrective action: The diaphragm acceptance criterion now requires a 10x magnification inspection of the diaphragm surface condition. B-EMU-135-A001 (10-6-88) The 135 valve failed to reseat due to excessive contamination drying on the diaphragm and valve seat after the PLSS was stored for over a year. Corrective action: Prior to the 135 crack and reseat test, a 135 valve which has not undergone a crack/reseat test in the last 30 days will be subjected to maximum water flow for five minutes. The 135 crack and reseat test will then be performed.
				H-EMU-135-D007 (11/09/95) - Item 135 Feedwater Relief Valve S/N 007 exceeded leakage during acceptance testing with 0.023 cc/hr vs. spec of 0.01 cc/hr. A new diaphragm and seat were installed and leakage increased to 0.033 cc/hr. Valve was tested over a six month period with no significant change. Analysis showed that the valve leakage could be increased without impacting overall PLSS leakage limit. EC 182135-023 increased internal water leakage from .01 cc/hr to .05 cc/hr.
				E. Ground Turnaround - Tested for non-EET processing per FEMU-R-001, water servicing, leakage and gas removal. None for EET processing.
				F. Operational Use - Crew Response - EVA: When CWS data confirms activation of reserve water tank, terminate EVA. Training - Standard EMU training covers this failure mode. Operational Considerations - Flight rules require termination of EVA when minimum primary consumables remain. EVA checklist procedures verify hardware integrity and systems operational status prior to EVA. Real Time Data System allows ground monitoring of EMU systems.

EXTRAVEHICULAR MOBILITY UNIT

SYSTEMS SAFETY REVIEW PANEL REVIEW

FOR THE

I-135 FEEDWATER RELIEF VALVE

CRITICAL ITEM LIST (CIL)

EMU CONTRACT NO. NAS 9-97150

Prepared by: HS - Project Engineering Approved by: TMB

M. Smpler HS - Reliability

Ula flough for HS - Engineering Manager RM

m