

**CRITICAL ITEMS LIST**

PROJECT: SRMS

ASS'Y NOMENCLATURE: SERVO POWER AMPLIFIER

SYSTEM: ELECTRICAL SUBSYSTEM

ASS'Y P/R: 51160F1377

SHEET: 1

FMEA REF.	FMEA REV.	NAME, QTY & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HDMR / FUNC. Z/TR CRITICALITY RATIONALE FOR ACCEPTANCE SCREENS: A-PASS, B-PASS, C-PASS
2780	1	STATUS DECODER LOGIC QTY-6 SCHEMATIC 2563721 AND 2563719	<p>MODE: DIRECTION FLAG DOES NOT CORRESPOND WITH ACTUAL DIRECTION OF MOTOR.</p> <p>CAUSE(S): (1) U21 PIN 15 FAILS.</p>	<p>TACHO DATA TO GPC HAS SIGN REVERSAL. NO EFFECT ON JOINT. LOSS OF LIMPING DURING END EFFECTOR CAPTURE.</p> <p>WORST CASE ----- LOSS OF MISSION. LOSS OF COMPUTER SUPPORTED MODES.</p> <p>REDUNDANT PATHS REMAINING ----- DIRECT AND BACKUP</p>	<p>DESIGN FEATURES -----</p> <p>THE DESIGN UTILIZES PROVEN CIRCUIT TECHNIQUES AND IS IMPLEMENTED USING CMOS LOGIC DEVICES.</p> <p>CMOS DEVICES OPERATE AT LOW POWER AND HENCE DO NOT EXPERIENCE SIGNIFICANT OPERATING STRESSES. THE TECHNOLOGY IS MATURE, AND DEVICE RELIABILITY HISTORY IS WELL DOCUMENTED. ALL STRESSES ARE ADDITIONALLY REDUCED BY DERATING THE APPROPRIATE PARAMETERS IN ACCORDANCE WITH SPAR-RMS-PA.003. SPECIAL HANDLING PRECAUTIONS ARE USED AT ALL STAGES OF MANUFACTURE TO PRECLUDE DAMAGE/STRESS DUE TO ELECTROSTATIC DISCHARGE.</p>

RMS/ELEC - 501

PREPARED BY: MWG

SUPERCEDING DATE: 06 OCT 87

APPROVED BY: \_\_\_\_\_

DATE: 24 JUL 91

CIL REV: 2

**CRITICAL ITEM LIST**

PROJECT: SRMS

ASSY NOMENCLATURE: SERVO FORM 6

SYSTEM: ELECTRICAL SUBSYSTEM

ASSY P/N: S1140F1177

REV: 2

ITEM REF.	ITEM REV.	NAME, QTY, & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HOUR / FUNC. 2/1R CRITICALITY RATIONALE FOR ACCEPTANCE SCREENS: A-PASS, B-PASS, C-PASS
2780	1	STATUS DECODER LOGIC QTY-6 SCHEMATIC 2563721 AND 2563719	<p>MODE: DIRECTION FLAG DOES NOT CORRESPOND WITH ACTUAL DIRECTION OF MOTOR.</p> <p>CAUSE(S): (1) U21 PIN 15 FAILS.</p>	<p>TACHO DATA TO CPC HAS SIGN REVERSAL. NO EFFECT ON JOINT. LOSS OF LIMPING DURING END EFFICIOR CAPTURE.</p> <p>WORST CASE ----- LOSS OF MISSION. LOSS OF COMPUTER SUPPORTED MODES.</p> <p>REDUNDANT PATHS REMAINING ----- DIRECT AND BACKUP</p>	<p>ACCEPTANCE TESTS ----- THE SPA IS SUBJECTED TO THE FOLLOWING ENVIRONMENTAL TESTING AS AN SRU.</p> <ul style="list-style-type: none"> <li>O VIBRATION: LEVEL AND DURATION - REFERENCE TABLE 4</li> <li>O THERMAL: PLUS 70 DEGREES C TO -25 DEGREES C DURATION - 1 1/2 CYCLES</li> </ul> <p>THE SPA IS THEN TESTED AS PART OF THE JOINTS ACCEPTANCE TESTS (VIBRATION AND THERMAL VACUUM TEST).</p> <p>THE SPA'S/JOINTS UNDERGO RMS SYSTEM TESTS (1PS18 RMS STRONGBACK AND 1PS52 FLAT FLOOR TESTS) WHICH VERIFIES THE ABSENCE OF THE FAILURE MODE.</p> <p>QUALIFICATION TESTS ----- THE SPA IS SUBJECTED TO THE FOLLOWING SRU QUALIFICATION TEST ENVIRONMENTS. THE SPA WAS ALSO TESTED AS PART OF THE JOINT QUALIFICATION TESTS.</p> <ul style="list-style-type: none"> <li>O VIBRATION: LEVEL AND DURATION - REFERENCE TABLE 4</li> <li>O SHOCK: 20G/11 MS/3 AXES (6 DIRECTIONS)</li> <li>O THERMAL VAC: +81 DEGREES C TO -36 DEGREES C (6 CYCLES) 1K10**6 TORR</li> <li>O HUMIDITY: TESTED WITH THE SHOULDER JOINT</li> <li>O EMC: MIL-STD-461 AS MODIFIED BY SI-E-0002 (TEST CE01, CE03, CS01, CS02, CS06, RE01, RE02 (N/B), RS01)</li> </ul> <p>FLIGHT CHECKOUT ----- PDRS OPS CHECKLIST (ALL VEHICLES) JSC 16987</p>

PREPARED BY: MFUG

SUPERCEDING DATE: 06 OCT 87

APPROVED BY: \_\_\_\_\_

DATE: 24 JUL 91

CIL REV: 2

RMS/ELEC - 502

**CRITICAL ITEM LIST**

PROJECT: SRMS  
ASS'Y NOMENCLATURE: SERVO POWER AMPLIFIER

SYSTEM: ELECTRICAL SUBSYSTEM  
ASS'Y P/N: 51120F1177

SHEET: 3

FMEA REF.	FMEA REV.	NAME, QTY, & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT OR END ITEM	HOWR / FUNC. Z/IN CRITICALITY	RATIONALE FOR ACCEPTANCE SCREENS: A-PASS, B-PASS, C-PASS
2780	1	STATUS DECODER LOGIC QTY-8 SCHEMATIC 2563721 AND 2563719	<p>MODE: DIRECTION FLAG DOES NOT CORRESPOND WITH ACTUAL DIRECTION OF MOTOR.</p> <p>CAUSE(S): (1) U21 PIN IS FAILS.</p>	<p>TACHO DATA TO GPC HAS SIGN REVERSAL, NO EFFECT ON JOINT. LOSS OF LIMPING DURING END EFFECTOR CAPTURE.</p> <p>WORST CASE</p> <p>LOSS OF MISSION. LOSS OF COMPUTER SUPPORTED MODES.</p> <p>REDUNDANT PATHS REMAINING</p> <p>DIRECT AND BACKUP</p>	<p>QA/INSPECTIONS</p> <p>UNITS ARE MANUFACTURED UNDER DOCUMENTED QUALITY CONTROLS. THESE CONTROLS ARE EXERCISED THROUGHOUT DESIGN PROCUREMENT, PLANNING, RECEIVING, PROCESSING, FABRICATION, ASSEMBLY, TESTING AND SHIPPING OF THE UNITS. MANDATORY INSPECTION POINTS ARE EMPLOYED AT VARIOUS STAGES OF FABRICATION ASSEMBLY AND TEST. GOVERNMENT SOURCE INSPECTION IS INVOKED AT VARIOUS CONTROL LEVELS.</p> <p>EEE PARTS INSPECTION IS PERFORMED AS REQUIRED BY SPAR-RMS-PA.003. EACH EEE PART IS QUALIFIED AT THE PART LEVEL TO THE REQUIREMENTS OF THE APPLICABLE SPECIFICATION. ALL EEE PARTS ARE 100% SCREENED AND BURNED IN, AS A MINIMUM, AS REQUIRED BY SPAR-RMS-PA.003, BY THE SUPPLIER. ADDITIONALLY, EEE PARTS ARE 100% RE-SCREENED IN ACCORDANCE WITH REQUIREMENTS, BY AN INDEPENDENT SPAR APPROVED TESTING FACILITY. DPA IS PERFORMED AS REQUIRED BY PA.003 ON A RANDOMLY SELECTED 5% OF PARTS, MAXIMUM 5 PIECES, MINIMUM 3 PIECES FOR EACH LOT NUMBER/DATE CODE OF PARTS RECEIVED.</p> <p>WIRE IS PROCURED TO SPECIFICATION MIL-W-22759 OR MIL-Q-81381 AND INSPECTED AND TESTED TO NASA JSC8000 STANDARD NUMBER 95A.</p> <p>RECEIVING INSPECTION VERIFIES THAT ALL PARTS RECEIVED ARE AS IDENTIFIED IN THE PROCUREMENT DOCUMENTS, THAT NO PHYSICAL DAMAGE HAS OCCURRED TO PARTS DURING SHIPMENT, THAT THE RECEIVING DOCUMENTS PROVIDE ADEQUATE TRACEABILITY INFORMATION AND SCREENING DATA CLEARLY IDENTIFIES ACCEPTABLE PARTS.</p> <p>PARTS ARE INSPECTED THROUGHOUT MANUFACTURE AND ASSEMBLY AS APPROPRIATE TO THE MANUFACTURING STAGE COMPLETED. THESE INSPECTIONS INCLUDE,</p> <p>PRINTED CIRCUIT BOARD INSPECTION FOR TRACK SEPARATION, DAMAGE AND ADEQUACY OF PLATED THROUGH HOLES,</p> <p>COMPONENT MOUNTING INSPECTION FOR CORRECT SOLDERING, WIRE LOOPING, STRAPPING, ETC. OPERATORS AND INSPECTORS ARE TRAINED AND CERTIFIED TO NASA MHB 5300.4(3A) STANDARD, AS MODIFIED BY JSC 0800A.</p> <p>CONFORMAL COATING INSPECTION FOR ADEQUATE PROCESSING IS PERFORMED USING ULTRAVIOLET LIGHT TECHNIQUES.</p> <p>POST P.C. BD. INSTALLATION INSPECTION, CLEANLINESS AND WORKMANSHIP (SPAR/GOVERNMENT REP. MANDATORY INSPECTION POINT)</p> <p>P.C. BD. INSTALLATION INSPECTION, CHECK FOR CORRECT BOARD INSTALLATION, ALIGNMENT OF BOARDS, PROPER CONNECTOR CONTACT MATING, WIRE ROUTING, STRAPPING OF WIRES ETC.,</p> <p>PRE-CLOSURE INSPECTION, WORKMANSHIP AND CLEANLINESS (SPAR/GOVERNMENT REP. - MANDATORY INSPECTION POINT)</p> <p>PRE-ACCEPTANCE TEST INSPECTION, WHICH INCLUDES AN AUDIT OF LOWER TIER INSPECTION COMPLETION, AS BUILT CONFIGURATION VERIFICATION TO AS DESIGN ETC., (MANDATORY INSPECTION POINT).</p>	

PREPARED BY: MFWD

SUPERSEDING DATE: 06 OCT 87

APPROVED BY: \_\_\_\_\_

DATE: 24 JUL 91

CIL REV: 2

RMS/ELEC - 503

**CRITICAL ITEM LIST**

PROJECT: SRMS  
 ASSY Nomenclature: SERVO POWER AMPLIFIER

SYSTEM: ELECTRICAL SUBSYSTEM  
 ASSY P/N: 51140F1177

SHEET: 4

IPIA REF.	IPIA REV.	NAME, QTY, & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HOUR / FUNC. 2/1R CRITICALITY RATIONALE FOR ACCEPTANCE SCREENS: A-PASS, B-PASS, C-PASS
2780	1	STATUS DECODER LOGIC QTY-A SCHEMATIC 2563721 AND 2563719	MODE: DIRECTION FLAG DOES NOT CORRESPOND WITH ACTUAL DIRECTION OF MOTOR.  CAUSE(S): (1) U21 PIN 15 FAILS.	TACHO DATA TO GPC HAS SIGN REVERSAL. NO EFFECT ON JOINT. LOSS OF LIMPING DURING END EFFECTOR CAPTURE.  WORST CASE ----- LOSS OF MISSION. LOSS OF COMPUTER SUPPORTED MODES.  REDUNDANT PATHS REMAINING ----- DIRECT AND BACKUP	<p>A TEST READINESS REVIEW (TRR) WHICH INCLUDES VERIFICATION OF TEST PERSONNEL, TEST DOCUMENTS, TEST EQUIPMENT CALIBRATION/ VALIDATION STATUS AND HARDWARE CONFIGURATION IS CONVENED BY QUALITY ASSURANCE IN CONJUNCTION WITH ENGINEERING, RELIABILITY, CONFIGURATION CONTROL, SUPPLIER AS APPLICABLE, AND THE GOVERNMENT REPRESENTATIVE, PRIOR TO THE START OF ANY FORMAL TESTING (ACCEPTANCE OR QUALIFICATION).</p> <p>ACCEPTANCE TESTING (ATP) INCLUDES AMBIENT PERFORMANCE, THERMAL AND VIBRATION TESTING, (SPAR/GOVERNMENT REP. - MANDATORY INSPECTION POINT).</p> <p>INTEGRATION OF UNIT TO JOINT SRU - INSPECTIONS INCLUDE GROUNDING CHECKS, CONNECTORS FOR BENT OR PUSHBACK CONTACTS, VISUAL, CLEANLINESS, INTERCONNECT WIRING AND POWER UP TEST TO THE APPROPRIATE JOINT INSPECTION TEST PROCEDURE (IIP) ETC.</p> <p>JOINT LEVEL PRE-ACCEPTANCE TEST INSPECTION, INCLUDES AN AUDIT OF LOWER TIER INSPECTION COMPLETION, AS BUILT CONFIGURATION VERIFICATION TO AS DESIGN ETC.</p> <p>JOINT LEVEL ACCEPTANCE TESTING (ATP) INCLUDES AMBIENT, VIBRATION AND THERMAL-VAC TESTING. (SPAR/GOVERNMENT REP. - MANDATORY INSPECTION POINT).</p> <p>SRMS SYSTEMS INTEGRATION, THE INTEGRATION OF MECHANICAL ARM SUBASSEMBLIES AND THE FLIGHT CABIN EQUIPMENT TO FORM THE SRMS. INSPECTIONS ARE PERFORMED AT EACH PHASE OF INTEGRATION WHICH INCLUDES GROUNDING CHECKS, THRU WIRING CHECKS, WIRING ROUTING, INTERFACE CONNECTORS FOR BENT OR PUSH BACK CONTACTS ETC.</p> <p>SRMS SYSTEMS TESTING - STRONGBACK AND FLAT FLOOR AMBIENT PERFORMANCE TEST. (SPAR/GOVERNMENT REP. - MANDATORY INSPECTION POINT)</p>

RMS/ELEC - 504

PREPARED BY: MFVG

SUPERSEDING DATE: 06 OCT 87

APPROVED BY: \_\_\_\_\_

DATE: 24 JUL 91

CIL REV: 2

**CRITICAL ITEMS LIST**

PROJECT: SRMS  
 ASS'Y NOMENCLATURE: SERVO POWER AMPLIFIER

SYSTEM: ELECTRICAL SUBSYSTEM  
 ASS'Y P/N: 512401177

SHEET: 5

IMEA REF.	IMEA REV.	NAME, QTY, & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HOWR / FUNC. Z/IR CRITICALITY RATIONALE FOR ACCEPTANCE SCREENS: A-PASS, B-PASS, C-PASS
2780	1	STATUS DECODER LOGIC QTY 6 SCHEMATIC 2563721 AND 2563719	MODE 1 DIRECTION FLAG DOES NOT CORRESPOND WITH ACTUAL DIRECTION OF MOTOR.  CAUSE(S): (1) U21 PIN 15 FAILS.	TACHO DATA TO GPC HAS SIGN REVERSAL. NO EFFECT ON JOINT. LOSS OF LIMPING DURING END EFFECTOR CAPTURE.  WORST CASE ----- LOSS OF MISSION. LOSS OF COMPUTER SUPPORTED MODES.  REDUNDANT PATHS REMAINING ----- DIRECT AND BACKUP	FAILURE HISTORY ----- THE FOLLOWING FAILURE ANALYSIS REPORT(S) ARE RELEVANT:  FAR 3046: S/N 211 AUG 79 ----- DESCRIPTION ----- SSC TEST, DIRECTION FLAG REMAINED ON. U17 OPEN CIRCUIT DUE TO ELECTRICAL SHORT OF UNKNOWN ORIGIN. ----- CORRECTIVE ACTION ----- REPL. U17  FAR 3047: S/N 204 AUG 79 ----- DESCRIPTION ----- SAME AS 3046. (COMPONENT IS CMOS CD 4049 AK BUFFER) ----- CORRECTIVE ACTION ----- REPL. U17

RMS/ELEC - 505

PREPARED BY: M/LWG

SUPERSEDING DATE: 06 OCT 87

APPROVED BY: \_\_\_\_\_

DATE: 24 JUL 91

EIL REV: 2

CIL

FORM 3.191

ASSY P/N:

SYSTEM: ELECTRICAL SUBS  
ASSY P/N: 5134071177

SHEET: 6

FMEA REF.	FMEA REV.	NAME, QTY, & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HOWR / FUNC. 2/1R CRITICALITY RATIONALE FOR ACCEPTANCE SCREENS: A-PASS, B-PASS, C-PASS
2780	1	STATUS DECODER LOGIC QTY-B SCHEMATIC 2561721 AND 2561719	<p>MODE: DIRECTION FLAG DOES NOT CORRESPOND WITH ACTUAL DIRECTION OF MOTOR.</p> <p>CAUSE(S): (1) U21 PIN 15 FAILS.</p>	<p>TACHO DATA TO GPC HAS SIGN REVERSAL. NO EFFECT ON JOINT. LOSS OF LIMPING DURING END EFFECTOR CAPTURE.</p> <p>WORST CASE ----- LOSS OF MISSION. LOSS OF COMPUTER SUPPORTED MODES.</p> <p>REDUNDANT PATHS REMAINING ----- DIRECT AND BACKUP</p>	<p>OPERATIONAL EFFECTS ----- COMPUTER SUPPORTED MODES CANNOT BE USED TO COMPLETE THE MISSION. DIRECT DRIVE AND RACK-UP MODES REMAIN. IF PAYLOAD ATTACHED, THE ARM SHOULD BE MANEUVERED TO A SAFE POSITION FOR PAYLOAD RELEASE. LOSS OF NEXT REDUNDANT PATH RESULTS IN BEING ONE FAILURE AWAY FROM INABILITY TO CRADLE ARM. IF WITH SUBSEQUENT FAILURES ALL DRIVE MODES ARE LOST, THE ARM MAY BE JETTISONED.</p> <p>CREW ACTION ----- USE DIRECT DRIVE</p> <p>CREW TRAINING ----- NONE</p> <p>MISSION CONSTRAINT ----- NONE</p> <p>OMRSD OFFLINE ----- DRIVE EACH JOINT IN COMPUTER CONTROLLED MODE. VERIFY THAT MOTOR DIRECTION FLAG AGREES WITH COMMAND DIRECTION.</p> <p>OMRSD ONLINE INSTALLATION ----- NONE</p> <p>OMRSD ONLINE TURNDOWN ----- IN SINGLE MODE, DRIVE EACH JOINT. VERIFY TACHOMETER SIGNATURE.</p>

RMS/ELEC - 506

PREPARED BY: MFVG

SUPERCEDING DATE: 06 OCT 87

APPROVED BY: \_\_\_\_\_

DATE: 24 JUL 91

CIL REV: 2