

**CRITICAL ITEM# LIST**

PROJECT: SRMS

SYSTEM: ELECTRICAL SUBSYSTEM

ASS'Y NOMENCLATURE: SERVO POWER AMPLIFIER

ASS'Y P/N: 51120F1177

SHEET: 1

FMEA REF.	FMEA REV.	NAME, QTY, & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT OR END ITEM	MODEL / FUNC. 2/1R CRITICALITY RATIONALE FOR ACCEPTANCE SCREENS: A-PASS, B-PASS, C-PASS
2800	1	TIMING AND LOGIC CONTROL QTY: 6 SCHEMATIC 2563719	<p>MODE: LOSS OF TIMING CONTROL.</p> <p>CAUSE(S):</p> <p>(1) OSCILLATOR FAILURE.</p> <p>(2) DIVIDERS.</p>	<p>TIMING LOST, TACHO DRIVE LOST. 1.6 MHZ MDA CLOCK LOST JOINT WILL FAIL FREE.</p> <p>INDUCTOSYN DRIVE LOST. PLL WILL GO OUT OF LOCK.</p> <p>ARM MAY TAKE AN UNEXPECTED TRAJECTORY. TACH BITE WILL INITIATE AUTO BRAKES.</p> <p>COMM. SCANNER BITE INOPERATIVE. LOSS OF LINING DURING END EFFECTOR CAPTURE.</p> <p>WORST CASE</p> <p>UNEXPECTED MOTION. FREE JOINT. AUTO BRAKES.</p> <p>REDUNDANT PATHS REMAINING</p> <p>AUTOBRAKES</p>	<p>DESIGN FEATURES</p> <p>-----</p> <p>THE 1.6 MHZ CLOCK IS GENERATED BY A HYBRID 3.2 MHZ CRYSTAL OSCILLATOR. THIS DEVICE UTILIZES ESTABLISHED RELIABILITY LIFE PARTS. THE DEVICE IS CONTROLLED BY SPAR PROCUREMENT SPECIFICATIONS WHICH INCLUDES THE REQUIREMENT FOR PRE-CAP VISUAL INSPECTION.</p> <p>THE DESIGN UTILIZES PROVEN CIRCUIT TECHNIQUES AND IS IMPLEMENTED USING CMOS LOGIC DEVICES.</p> <p>CMOS DEVICES OPERATE AT LOW POWER AND HENCE DO NOT EXPERIENCE SIGNIFICANT OPERATING STRESSES. THE TECHNOLOGY IS MATURE, AND DEVICE RELIABILITY HISTORY IS WELL DOCUMENTED. ALL STRESSES ARE ADDITIONALLY REDUCED BY DERATING THE APPROPRIATE PARAMETERS IN ACCORDANCE WITH SPAR-RMS-PA.003. SPECIAL HANDLING PRECAUTIONS ARE USED AT ALL STAGES OF MANUFACTURE TO PRECLUDE DAMAGE/STRESS DUE TO ELECTROSTATIC DISCHARGE.</p>

RMS/ELEC - 513

PREPARED BY: MEWG

SUPERCEDING DATE: 06 OCT 87

APPROVED BY: \_\_\_\_\_

DATE: 24 JUL 91

CIL REV: 2

**CRITICAL ITEM LIST**

PROJECT: SRMS

ASSY NAME/PART NUMBER: SERVO POWER AMPLIFIER

SYSTEM: ELECTRICAL SUBSYSTEM  
 A/CY P/R: 51140P1177

SHEET: 2

EMEA REF.	EMEA REV.	NAME, QTY, & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT OR END ITEM	HOW / FUNC. Z/FW CRITICALITY	RATIONALE FOR ACCEPTANCE SCREENS: A-PASS, B-PASS, C-PASS
2000	1	TIMING AND LOGIC CONTROL QTY: 6 SCHEMATIC 2561719	<p>MODE: LOSS OF TIMING CONTROL.</p> <p>CAUSE(S):                      (1) OSCILLATOR FAILURE.                      (2) DIVIDERS.</p>	<p>TIMING LOSS, TACHO DRIVE LOST. 1.6 MHZ MDA CLOCK LOSE JOINT WILL FAIL FREE.</p> <p>INDUCTOSYN DRIVE LOST. PLL WILL GO OUT OF LOCK.</p> <p>ARM MAY TAKE AN UNEXPECTED TRAJECTORY. TACH BITE WILL INITIATE AUTO BRAKES.</p> <p>CONN. SCANNER BITE INOPERATIVE.</p> <p>LOSS OF LIMPING DURING END EFFECTOR CAPTURE.</p> <p>WORST CASE                      UNEXPECTED MOTION. FREE JOINT. AUTO BRAKES.</p> <p>REDUNDANT PATHS REMAINING                      -----                      AUTOBRAKES</p>	<p>ACCEPTANCE TESTS                      -----                      THE SPA IS SUBJECTED TO THE FOLLOWING ENVIRONMENTAL TESTING AS AN SRU.</p> <p>O VIBRATION: LEVEL AND DURATION - REFERENCE TABLE 4</p> <p>O THERMAL: PLUS 70 DEGREES C TO -25 DEGREES C DURATION - 1 1/2 CYCLES</p> <p>THE SPA IS THEN TESTED AS PART OF THE JOINTS ACCEPTANCE TESTS (VIBRATION AND THERMAL VACUUM TEST).</p> <p>THE SPA'S/JOINTS UNDERGO RMS SYSTEM TESTS (TPS18 RMS STRONGBACK AND 1PSS2 FLAT FLOOR TESTS) WHICH VERIFIES THE ABSENCE OF THE FAILURE MODE.</p> <p>QUALIFICATION TESTS                      -----                      THE SPA IS SUBJECTED TO THE FOLLOWING SRU QUALIFICATION TEST ENVIRONMENTS. THE SPA WAS ALSO TESTED AS PART OF THE JOINT QUALIFICATION TESTS.</p> <p>O VIBRATION: LEVEL AND DURATION - REFERENCE TABLE 4</p> <p>O SHOCK: 20G/11 MS/3 AXES (6 DIRECTIONS)</p> <p>O THERMAL VAC: +01 DEGREES C TO -36 DEGREES C (6 CYCLES) 1K10**6 TORR</p> <p>O HUMIDITY: TESTED WITH THE SHOULDER JOINT</p> <p>O EMC: MIL-STD-461 AS MODIFIED BY SL-E-0002 (TEST CE01, CE03, CS01, CS02, CS06, RE01, RE02 (N/B), RS01)</p> <p>FLIGHT CHECKOUT                      -----                      PORS OPS CHECKLIST (ALL VEHICLES) JSC 16987</p>	

PREPARED BY:

MFWD

SUPERCEDING DATE: 06 OCT 87

APPROVED BY:

DATE: 26 JUL 91

CIL REV: 2

RMS/ELEC - 514

**CRITICAL ITEMS LIST**

PROJECT: RMS

SYSTEM: ELECTRICAL SUBSYSTEM

ASSY NAME/CONFIGURE: SERVO POWER AMPLIFIER

ASSY P/N: 51120F177

SHEET: 3

TIMEA REV.	TIMEA REV.	DRAWN BY & DRAWING OFF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	MDWR / FUNC. 2/TR CRITICALITY	RATIONALE FOR ACCEPTANCE SCREENS: A-PASS, B-PASS, C-PASS
2000	1	TIMING AND IDLE CONTROL QTY 6 SCHEMATIC 2561719	<p>MODE: LOSS OF TIMING CONTROL.</p> <p>CAUSE(S): (1) OSCILLATOR FAILURE. (2) DIVIDERS.</p>	<p>TIMING LOST, TACHO DRIVE LOST, 1.6 MHZ MDA CLOCK LOST JOINT WILL FAIL FREE.</p> <p>INDUCTOSYN DRIVE LOST, PLL WILL GO OUT OF LOCK.</p> <p>ARM MAY TAKE AN UNEXPECTED TRAJECTORY. TACHO BITE WILL INITIATE AUTO BRAKES.</p> <p>COMM. SCANNER BITE INOPERATIVE.</p> <p>LOSS OF LIMPING DURING END EFFECTOR CAPTURE.</p> <p>WORST CASE ----- UNEXPECTED MOTION, FREE JOINT, AUTO BRAKES.</p> <p>REDUNDANT PATHS REMAINING ----- AUTOBRAKES</p>	<p>QA/INSPECTIONS</p> <p>UNITS ARE MANUFACTURED UNDER DOCUMENTED QUALITY CONTROLS. THESE CONTROLS ARE EXERCISED THROUGHOUT DESIGN PROCUREMENT, PLANNING, RECEIVING, PROCESSING, FABRICATION, ASSEMBLY, TESTING AND SHIPPING OF THE UNITS. MANDATORY INSPECTION POINTS ARE EMPLOYED AT VARIOUS STAGES OF FABRICATION ASSEMBLY AND TEST. GOVERNMENT SOURCE INSPECTION IS INVOKED AT VARIOUS CONTROL LEVELS.</p> <p>EEE PARTS INSPECTION IS PERFORMED AS REQUIRED BY SPAR-RMS-PA.003. EACH EEE PART IS QUALIFIED AT THE PART LEVEL TO THE REQUIREMENTS OF THE APPLICABLE SPECIFICATION. ALL EEE PARTS ARE 100% SCREENED AND BURNED IN, AS A MINIMUM AS REQUIRED BY SPAR-RMS-PA.003, BY THE SUPPLIER. ADDITIONALLY, EEE PARTS ARE 100% RE-SCREENED IN ACCORDANCE WITH REQUIREMENTS, BY AN INDEPENDENT SPAR APPROVED TESTING FACILITY. DPA IS PERFORMED AS REQUIRED BY PA.003 ON A RANDOMLY SELECTED 5% OF PARTS, MAXIMUM 5 PIECES, MINIMUM 3 PIECES FOR EACH LOT NUMBER/DATE CODE OF PARTS RECEIVED.</p> <p>WIRE IS PROCURED TO SPECIFICATION MIL-W-22759 OR MIL-W-81301 AND INSPECTED AND TESTED TO NASA JSCM000 STANDARD NUMBER 95A.</p> <p>RECEIVING INSPECTION VERIFIES THAT ALL PARTS RECEIVED ARE AS IDENTIFIED IN THE PROCUREMENT DOCUMENTS, THAT NO PHYSICAL DAMAGE HAS OCCURRED TO PARTS DURING SHIPMENT, THAT THE RECEIVING DOCUMENTS PROVIDE ADEQUATE TRACEABILITY INFORMATION AND SCREENING DATA CLEARLY IDENTIFIES ACCEPTABLE PARTS.</p> <p>PARTS ARE INSPECTED THROUGHOUT MANUFACTURE AND ASSEMBLY AS APPROPRIATE TO THE MANUFACTURING STAGE COMPLETED. THESE INSPECTIONS INCLUDE,</p> <p>PRINTED CIRCUIT BOARD INSPECTION FOR TRACK SEPARATION, DAMAGE AND ADEQUACY OF PLATED THROUGH HOLES,</p> <p>COMPONENT MOUNTING INSPECTION FOR CORRECT SOLDERING, WIRE LOOPING, STRAPPING, ETC. OPERATORS AND INSPECTORS ARE TRAINED AND CERTIFIED TO NASA WHD 5300.4(3A) STANDARD, AS MODIFIED BY JSC 08800A.</p> <p>CONFORMAL COATING INSPECTION FOR ADEQUATE PROCESSING IS PERFORMED USING ULTRAVIOLET LIGHT TECHNIQUES.</p> <p>POST P.C. BD. INSTALLATION INSPECTION, CLEANLINESS AND WORKMANSHIP (SPAR/GOVERNMENT REP. MANDATORY INSPECTION POINT)</p> <p>P.C. BD. INSTALLATION INSPECTION, CHECK FOR CORRECT BOARD INSTALLATION, ALIGNMENT OF BOARDS, PROPER CONNECTOR CONTACT MATING, WIRE ROUTING, STRAPPING OF WIRES ETC.,</p> <p>PRE-CLOSURE INSPECTION, WORKMANSHIP AND CLEANLINESS (SPAR/GOVERNMENT REP. - MANDATORY INSPECTION POINT)</p> <p>PRE-ACCEPTANCE TEST INSPECTION, WHICH INCLUDES AN AUDIT OF LOWER TIER INSPECTION COMPLETION, AS BUILT CONFIGURATION VERIFICATION TO AS DESIGN ETC., (MANDATORY INSPECTION POINT).</p>	

PREPARED BY:

MJUG

SUPERSEDING DATE: 06 OCT 87

APPROVED BY:

DATE: 24 JUL 91

CIL REV: 2

RMS/ELEC - 515

ORIGINAL ITEM LIST

PROJECT: SRMS  
 ASSY IDENTIFICATION: STROVO POWER AMPLIFIER

SYSTEM: ELECTRICAL SUBSYSTEM  
 ASSY P/N: 51707177

SHEET: 4

ITEM REF.	QTY	PART, QTY, & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HOUR / FUNC. 2/1R CRITICALITY RATIONALE FOR ACCEPTANCE SCREENS: A-PASS, B-PASS, C-PASS
2600	1	TIMING AND LOGIC CONTROL QTY-6 SCHEMATIC 2563719	MODE: LOSS OF TIMING CONTROL.  CAUSE(S): (1) OSCILLATOR FAILURE.  (2) DIVIDERS.	TIMING LOST, TACHO DRIVE LOST. 1.6 MHZ MDA CLOCK LOST JOINT WILL FAIL FREE. INDUCTOSYN DRIVE LOST. PLL WILL GO OUT OF LOCK. ARM MAY TAKE AN UNEXPECTED TRAJECTORY. TACH BITE WILL INITIATE AUTO BRAKES. COMM. SCANNER BITE INOPERATIVE. LOSS OF LIMPING DURING END EFFECTOR CAPTURE.  WORST CASE ----- UNEXPECTED MOTION. FREE JOINT. AUTO BRAKES.  REDUNDANT PATHS REMAINING ----- AUTOBRAKES	<p>A TEST READINESS REVIEW (TRR) WHICH INCLUDES VERIFICATION OF TEST PERSONNEL, TEST DOCUMENTS, TEST EQUIPMENT CALIBRATION/ VALIDATION STATUS AND HARDWARE CONFIGURATION IS CONVENED BY QUALITY ASSURANCE IN CONJUNCTION WITH ENGINEERING, RELIABILITY, CONFIGURATION CONTROL, SUPPLIER AS APPLICABLE, AND THE GOVERNMENT REPRESENTATIVE, PRIOR TO THE START OF ANY FORMAL TESTING (ACCEPTANCE OR QUALIFICATION).</p> <p>ACCEPTANCE TESTING (ATP) INCLUDES AMBIENT PERFORMANCE, THERMAL AND VIBRATION TESTING, (SPAR/GOVERNMENT REP. - MANDATORY INSPECTION POINT).</p> <p>INTEGRATION OF UNIT TO JOINT SRU - INSPECTIONS INCLUDE GROUNDING CHECKS, CONNECTORS FOR BENT OR PUSHBACK CONTACTS, VISUAL, CLEANLINESS, INTERCONNECT WIRING AND POWER UP TEST TO THE APPROPRIATE JOINT INSPECTION TEST PROCEDURE (ITP) ETC.</p> <p>JOINT LEVEL PRE-ACCEPTANCE TEST INSPECTION, INCLUDES AN AUDIT OF LOWER TIER INSPECTION COMPLETION, AS BUILT CONFIGURATION VERIFICATION TO AS DESIGN ETC.</p> <p>JOINT LEVEL ACCEPTANCE TESTING (ATP) INCLUDES AMBIENT, VIBRATION AND THERMAL-VAC TESTING. (SPAR/GOVERNMENT REP. - MANDATORY INSPECTION POINT).</p> <p>SRMS SYSTEMS INTEGRATION, THE INTEGRATION OF MECHANICAL ARM SUBASSEMBLIES AND THE FLIGHT CABIN EQUIPMENT TO FORM THE SRMS. INSPECTIONS ARE PERFORMED AT EACH PHASE OF INTEGRATION WHICH INCLUDES GROUNDING CHECKS, THRU WIRING CHECKS, WIRING ROUTING, INTERFACE CONNECTORS FOR BENT OR PUSH BACK CONTACTS ETC.</p> <p>SRMS SYSTEMS TESTING - STRONGBACK AND FLAT FLOOR AMBIENT PERFORMANCE TEST. (SPAR/GOVERNMENT REP. - MANDATORY INSPECTION POINT)</p>

RMS/ELEC - 516

**CRITICAL ITEMS LIST**

PROJECT: SRMS

ASS'Y NOMENCLATURE: SERVO POWER AMPLIFIER

SYSTEM: ELECTRICAL SUBSYSTEM  
ASS'Y P/N: 51150P1177

SHEET: 5

FMEA REF.	FMEA REV.	NAME, QTY & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HOUR / FUNC. 2/1R CRITICALITY
2800	1	TIMING AND LOGIC CONTROL QTY: 6 SCHEMATIC 2563719	MODE: LOSS OF TIMING CONTROL.  CAUSE(S): (1) OSCILLATOR FAILURE.  (2) DIVIDERS.	TIMING LOST, TACHO DRIVE LOST, 1.6 MHZ MDA CLOCK LOST JOINT WILL FAIL FREE. INDUCTOSYN DRIVE LOST, PLL WILL GO OUT OF LOCK. ARM MAY TAKE AN UNEXPECTED TRAJECTORY. TACH BITE WILL INITIATE AUTO BRAKES. COMM. SCANNER BITE INOPERATIVE. LOSS OF LIMPING DURING END EFFECTOR CAPTURE.  WORST CASE UNEXPECTED MOTION. FREE JOINT. AUTO BRAKES.  REDUNDANT PATHS REMAINING AUTOBRAKES	RATIONALE FOR ACCEPTANCE SCREENS: A-PASS, B-PASS, C-PASS  FAILURE HISTORY ----- THERE HAVE BEEN NO FAILURES ASSOCIATED WITH THIS FAILURE MODE ON THE SRMS PROGRAM.

PREPARED BY:

MFVG

SUPERSEDING DATE: 06 OCT 87

APPROVED BY: \_\_\_\_\_

DATE: 26 JUL 91

CIL REV: 2

RMS/ELEC - 517

**CRITICAL ITEM LIST**

PROJECT: SRMS  
 ASS'Y NAME/PARTIAL: SERVO POWER AMPLIFIER

SYSTEM: ELECTRICAL SUBSYSTEM  
 ASS'Y P/N: 51140P1177

SHEET: 6

IMEA REF.	IMEA REV.	NAME, QTY, & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HOWR / TIME, 2/TR CRITICALITY	RATIONALE FOR ACCEPTANCE SCREENS: A-PASS, B-PASS, C-PASS
2800	1	TIMING AND LOGIC CONTROL QTY: 6 SCHEMATIC 2563719	MODE: LOSS OF TIMING CONTROL.  CAUSE(S): (1) OSCILLATOR FAILURE.  (2) DIVIDERS.	TIMING LOST, TACHO DRIVE LOST, 1.6 MHZ MDA CLOCK LOST JOINT WILL FAIL FREE. INDUCTOSYN DRIVE LOST, PLL WILL GO OUT OF LOCK. ARM MAY TAKE AN UNEXPECTED TRAJECTORY. TACH BITE WILL INITIATE AUTO BRAKES. COMM. SCANNER BITE INOPERATIVE. LOSS OF LIMPING DURING END EFFECTOR CAPTURE.  WORST CASE ----- UNEXPECTED MOTION. FREE JOINT. AUTO BRAKES.  REDUNDANT PATHS REMAINING ----- AUTOBRAKES		OPERATIONAL EFFECTS ----- ARM DOES NOT RESPOND PROPERLY TO HAND CONTROLLER COMMANDS OR AUTO SEQUENCES. AUTOBRAKES. CANNOT USE PRIMARY MODES OF OPERATION. ARM WILL NOT STOP AUTOMATICALLY IF AN UNDETECTED FAILURE OF THE AUTOBRAKES SYSTEM HAS PREVIOUSLY OCCURRED. BRAKES CAN BE APPLIED MANUALLY.  CREW ACTION ----- APPLY BRAKES. SELECT BACKUP.  CREW TRAINING ----- THE CREW WILL BE TRAINED TO OBSERVE WHETHER THE ARM IS RESPONDING PROPERLY TO COMMANDS. IF IT ISN'T, APPLY BRAKES.  MISSION CONSTRAINT ----- OPERATE UNDER VERNIER RATES WITHIN 10 FT OF STRUCTURE. THE OPERATOR MUST BE ABLE TO DETECT THAT THE ARM IS RESPONDING PROPERLY TO COMMANDS VIA WINDOW AND/OR CCTV VIEWS DURING ALL ARM OPERATIONS.  OMRSD OFFLINE ----- VERIFY ABSENCE OF TACH FAIL FLAG ON ABE DATA.  OMRSD ONLINE INSTALLATION ----- NONE  OMRSD ONLINE TURNDOWN ----- VERIFY ABSENCE OF TACH FAIL FLAG ON ABE DATA

PREPARED BY: HWG SUPERCEDING DATE: 06 OCT 87 APPROVED BY: \_\_\_\_\_ DATE: 24 JUL 91 CIL REV: 2

RMS/ELEC - 518