

12/24/93 SUPERSEDER 12/24/91

ANALYST:

NAME P/N QTY	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE												
DISPLAY AND CONTROLS MODULE, ITEM 300 ----- SV792294-05 (1)	2/2	SODPN06: IV position switch fails on (closed). CAUSE: Internal switch failure due to contact welding, jamming, or contamination, fractured braze joint, switch activation drift.	END ITEM: Unable to display actuator position when actuator is in IV. OPE INTERFACE: Unable to perform leak check. MISSION: None. If IV, terminate mission for inability to complete suit leak check. Loss of one EMU. CREW/VEHICLE: None.	A. Design - The 3 micro switches are hermetically sealed units which meet the requirements of MIL-S-8805/B (NS 27214-6). The internal contacts are gold plated to prevent corrosion. The external wiring to the switches is teflon insulated M22759/11. Soldering to the switch terminals is per NH 5300.4 (3A-1) The switch is mounted to a stop plate, and actuation is via a slide arm on the shearplate which together prevents switch damage due to inadvertent or excessive mechanical force. The switches are rated at 0.5 amperes. Actual current is 0.5 milliamperes. B. Test - Component Acceptance Test: The unit is tested per NI-S-8805 by the vendor. In-Process Test - Proper operation of the switches is verified during the completion of assembly of the O2 Actuator Switch Assembly (kit SV26788-02). Certification Test - The microswitches are qualified to MIL-S-8805/B (vendor is an OPL) which has a life requirement of 25,000 cycles minimum. The switches completed the 15 year structural vibration and shock certification during 10/83 and four hour thermal vacuum certification during 2/82, both as part of the DCN. The O2 Actuator Switch Assembly (kit SV26788-02) completed 15 year structural vibration and shock and thermal vacuum certification for the redesigned DCN during 7/86 and 8/86 as part of the DCN/308. In addition, the switch/slide arm assembly (DCN/Shearplate) was cycled for the following durations during 1/84: <table border="1"> <thead> <tr> <th>Position</th> <th>Actual</th> <th>Spec</th> </tr> </thead> <tbody> <tr> <td>IV</td> <td>1,323</td> <td>5,519</td> </tr> <tr> <td>OFF</td> <td>3,969</td> <td>10,040</td> </tr> <tr> <td>PRESS</td> <td>2,646</td> <td>6,069</td> </tr> </tbody> </table>	Position	Actual	Spec	IV	1,323	5,519	OFF	3,969	10,040	PRESS	2,646	6,069
Position	Actual	Spec														
IV	1,323	5,519														
OFF	3,969	10,040														
PRESS	2,646	6,069														

The remainder of the cycle testing was completed during
6/87.

12/24/93 SUPERSEDES 12/24/91

ANALYST:

NAME P/N QTY	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
	2/2	300FH04;		

C. Inspection -

At switch end stop (SV776113-3) assembly level, an inspection is done which cycles the switch while checking the distance for actuation. A broken switch would be detected at this point. Soldering of lead wires is inspected for compliance to NAS300.4 (3A-1) and the wires themselves are inspected for damage.

D. Failure History -
None.

E. Dround Turnaround -
Tested per FEMI-R-001, O2 Actuator Position Switch Check.

F. Operational Use -

Crew Response - PreEVA: Continus EVA operations. Perform all leak checks manually.

EVA: No response, single failure undetectable by crew or ground.

Training - Standard EMI training covers this failure mode.

Operational Considerations - For single failure, no constraints.