

CIL
Critical Item List

Assembly Name/Part Number: Reaction Arm Assembly/18137-0000
 Reference: CIL RARM
 Prepared By: C. Hartman
 Supervising Salar: (R/S)
 Approved By: M. Misher
 Date: 8/27/89

NAME SP/N QTY	CRIT	FAILURE MODE & CAUSE	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
Reaction Arm 18137- 0000 1000	1/1	3.3FN12 Fast to interface with Torque Multiplier. CAUSE: Defective material, Damage, impact, Thermal Expansion.	END ITEM: Unable to mate with Torque Multiplier. RFE INTERFACE: Unable to loosen lock bolts. MISSION: Terminate EVA, Unable to Jettison Payload. CREW/VEHICLE: Loss of crew and vehicle.	A. DESIGN: The Reaction Arm Housing is fabricated from Inconel 718, bar per AMS 5664. It is manufactured by Ruston International per Drawing G1878-504993. The Reaction Arm Assembly is stored in a foam cushion in the Payload Bay PSA to protect it from the possibility of damage from impact. B. TEST: Component Acceptance Test - None PSA Test - The following tests are conducted at the Reaction Arm Assembly level in accordance with IIC Document 18137-78638: 1. Functional test to verify proper interface with Torque Multiplier. Certification Test - The Reaction Arm Assembly was tested to S7AD requirements of night system and exhibited no evidence of damage. It was certified for the worst case PSA Storage temperature range of -50 degrees F to +150 degrees F and interfaced with the Torque Multiplier.

CIL
Critical Items List

Assembly Name/Part Number: Reaction Arm Assembly/10159-20240-01
 Reference: CIL_RARM
 Prepared By: C. Hartman
 Approved By: A. Withey
 Superseding Data: 9708
 Date: 1/29 Revs A

ISSUE P/R ID#	CRIT	FAILURE MODE & CAUSE	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
Heading 10070- 100199)-01 Item S.3 1000	1/1	S. 10W12 Fail to interface with Torque Multiplier.		<p>C: INSPECTION</p> <p>Components and material manufactured to ILC requirements at an approved supplier are documented from procurement through shipping by the supplier. ILC incoming receiving inspection verifies that the materials received are as identified in the procurement documents, that no damage has occurred during shipment and that supplier certification has been received which provides traceability information.</p> <p>The following WIP's are performed during the Reaction Arm Assembly manufacturing process to assure the failure causes are precluded from the fabricated item:</p> <ol style="list-style-type: none"> 1. Inspection for damage or material degradation. <p>During PMA, the following inspection points are performed at the Reaction Arm Assembly level in accordance with ILC Document 10107-70690:</p> <ol style="list-style-type: none"> 1. Inspection for damage or material degradation. 2. Verify successful completion of interface test. 3. Verify conformance to drawing.

**CIL
Critical Items List**

Assembly Name/Part Number: Reaction Arm Assembly/18157-20210-01
 Reference: CIL 0000
 Prepared By: C. Hartson
 Superseding Date: 9/00
 Approved By: H. Nolley
 Date: 1/09 Rev: A

NAME IP/N ID/N	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
INcoming 18010- 1804991-001 Item 2.3 18m 18m	1/1	S.2M12 Fail to interface with Torque Multiplier.		<p>D. FAILURE HISTORY: None</p> <p>E. BROUPE INMANAGEMENT: During ground turnaround, in accordance with BLC Document 18167-70213, the Reaction Arm Assembly is inspected for damage and proper operation.</p> <p>F. OPERATIONAL USE: 1. Crew Response Pre/Post EVA - N/A EVA - Transport back to crew compartment and attempt to repair.</p> <p>2. Training Crew briefing.</p> <p>3. Operational Considerations Catastrophic failure. Possible loss of crew/vehicle.</p>