

CIL
Critical Items List

Assembly Name/Part Number: Torque Multiplier/10139 JB.01 B1
 Reference: CIL_TROM1
 Prepared By: C. Hartman
 Supervising Date: 1/89
 Approved By: M. Mathey
 Date: 8/89 Rev: A

NAME IP/W IDEV	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
Torque Multiplier 10139- 128794-01 Item 5.9 10m	1/1	5.4PH11 Fails to interface with latch bolt. CAUSE: Defective material; impact, contamination, galling.	END ITEM Unable to interface with latch bolt. SPE INTERFACE: Unable to insert latch bolt. MISSION: Unable to Jettison Payload. Terminate EVA. CREW/VEHICLE: Loss of crew and vehicle.	A. DESIGN: The Torque Multiplier Socket is 1-1/16 inch 12-PT socket fabricated from 304B steel and is manufactured by Snap On Inc. The Torque Multiplier is allowed in a foam cushion in the Payload Bay PSA to protect it from the possibility of damage from impact. B. TEST: Component Acceptance Test - None PSA Test - The following tests are conducted at the Torque Multiplier Assembly level in accordance with ILC Document 10137-70650: 1. Functional test to verify proper operation. 2. Interface with latch bolt test fixture.

REVISION PART 0789
 84-26 84-31
 CH. 01

P. 397

FORM 84-25

CIL
Critical Items List

Assembly Name/Part Number: Torque Multiplier/100159 LM-33-01
Reference: CIL, IRMM-1
Prepared By: C. Hartman
Superseding Date: 1/89
Approved By: M. Mithay
Date: 8/83 Rev: A

NAME IP/N IDTY	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
Torque Multiplier 100159- 100159-01 Item 3.4 ID00	H/I	3.40111 Fails to interface with latch ball.		<p>Certification Test - The Torque Multiplier was tested to S/WB requirements of eight cycles and exhibited no evidence of damage. It was certified for the worst case PMA Storage temperature range of -200 degrees F to +320 degrees F.</p> <p>C. INSPECTION: Components and material manufactured to IIC requirements at an approved supplier are documented from procurement through shipping by the supplier. IIC incoming receiving inspection verifies that the materials received are as identified in the procurement documents, that no damage has occurred during shipment and that supplier certification has been received which provides traceability information.</p> <p>The following IIP's are performed during the Torque Multiplier Assembly manufacturing process to ensure the failure causes are precluded from the fabricated items:</p> <ol style="list-style-type: none"> 1. Inspection of all components for damage or material degradation. 2. Verify cleanliness to VC level.

REVISION: 12/89
 IAW: 84-25
 Ch.#1
 84-21
 P. 407

101
Critical Items List

Assembly Name/Part Number: Torque Multiplier (M102) - 0.00 01
 Reference: CII, IROPL
 Prepared By: C. Harrison
 Supervising Date: 1/82
 Approved By: H. Hitchey
 Date: 8/82 Rev: A

NAME IP/N IDY	CRII	FAILURE MODE & CAUSE	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
Torque Multiplier M102 1.0204 01 Time 2.4 000	1/1	S. 40111 Fail to interface with batch bolt.		<p>During PDR, the following inspection events are performed at the Torque Multiplier Assembly level in accordance with IIC Document M102-7000.</p> <ol style="list-style-type: none"> 1. Verify conformance to drawing. 2. Inspection for damage or material degradation. 3. Verification of successful completion of functional test and built interface. 4. Verify cleanliness to VC level. <p>D. FAILURE HISTORY None</p> <p>E. GROUND UNMARKED During ground turnaround, in accordance with IIC Document M102-70713, the Torque Multiplier Assembly is inspected for damage, functionally tested for proper operation and cleaned to VC level.</p> <p>F. OPERATIONAL ISS: 1. Crew Response Pre/Post EVA - N/A EVA - Transport Torque Multiplier to crew compartment and attempt to repair.</p>

REPL. INT. - 2-89
 84-26 2-84-31
 CH. 71
 P. 5 of 7

CIL
Critical Items List

Assembly Name/Part Number Torque Multiplier/18157 28,30 04
 Reference: CIL 18061
 Prepared By: C. Hartman
 Superseding Dates: 1/07
 Approved By: W. Hickey
 Date: 4/02 Rev: A

ITEM P/N REV	CRIT	FAILURE MODE & CAUSE	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
1 Torque Multiplier 18157- 18157-00 Rev 3.4 000	1/0	3.4FR00 Fail to interface with latch ball.		<ol style="list-style-type: none"> 1. Operational Considerations Catastrophic failure. Possible loss of crew/vehicle. 2. Training Crew training.

REVISIONS
 DATE: 07/09
 BY: Bc-27
 BY: Bc-21
 CA: #1

2.6087