

SSME FMEA/CIL
REDUNDANCY SCREEN

Component Group: Ducts and Lines
 CIL Item: K102-02
 Part Number: RS007034
 Component: LPFTP Turbine Drive Duct
 FMEA Item: K102
 Failure Mode: Piece part structural failure.

Prepared: D. Early
 Approved: T. Nguyen
 Approval Date: 7/25/00
 Change #: 1
 Directive #: CCBD ME3-01-5638

Page: 1 of 1

Phase	Failure / Effect Description	Criticality Hazard Reference
S 4.1	<p>Internal failure cause particle generation; piece flows downstream blocking LPFTP nozzle vane causing a loss of turbine power resulting in reduced output to the HPFTP. In the event of HPFTP cavitation, excessive turbine discharge temperatures results in a premature engine shutdown. Mission scrub. Loss of vehicle due to HPFTP turbine failure may result if overtemperature condition is not detected.</p> <p>Redundancy Screens: DUCT SYSTEM - SENSOR SYSTEM: UNLIKE REDUNDANCY</p> <p>A: Pass - Redundant hardware items are capable of checkout during normal ground turnaround. B: Pass - Loss of a redundant hardware items is detectable during flight. C: Pass - Loss of redundant hardware items could not result from a single credible event.</p>	1R ME-D1S,M
M 4.1	<p>Internal failure cause particle generation; piece flows downstream blocking LPFTP nozzle vane causing a loss of turbine power resulting in reduced output to the HPFTP. In the event of HPFTP cavitation, excessive turbine discharge temperatures results in a premature engine shutdown. Mission abort. Loss of vehicle due to HPFTP turbine failure may result if overtemperature condition is not detected.</p> <p>Redundancy Screens: DUCT SYSTEM - SENSOR SYSTEM: UNLIKE REDUNDANCY</p> <p>A: Pass - Redundant hardware items are capable of checkout during normal ground turnaround. B: Pass - Loss of a redundant hardware items is detectable during flight. C: Pass - Loss of redundant hardware items could not result from a single credible event.</p>	1R ME-D1S,M

**SSME E/CIL
DESIGN**

Component Group: Ducts and Lines
CIL Item: K102-02
Part Number: RS007034
Component: LPFTP Turbine Drive Duct
FMEA Item: K102
Failure Mode: Piece part structural failure.

Prepared: D. Early
Approved: T. Nguyen
Approval Date: 7/25/00
Change #: 1
Directive #: CCBD ME3-01-5638

Page: 1 of 1

Design / Document Reference

FAILURE CAUSE: A: Internal structural failure of: Stabilizer, Inlet/outlet sleeves/tubes, Welds.

THE FLEX JOINTS ARE DOUBLE BELLOWS WITH EXTERNAL GIMBAL LINKAGE. STABILIZER (1), AND INLET AND OUTLET SLEEVES (1) ARE MANUFACTURED UTILIZING INCOLOY 903. INCOLOY 903 WAS SELECTED FOR ITS STRENGTH AND ITS RESISTANCE TO HYDROGEN ENVIRONMENT EFFECTS. IT IS WELDABLE AND IS RESISTANT TO STRESS CORROSION CRACKING (2). INSTALLATION IS CONTROLLED FOR ANGULARITY AND OFFSET (3). MOVING PARTS INCORPORATE RADII ON ENDS TO PREVENT NARROW CONTACT POINTS AND LOADING. DURING OPERATION, PRESSURE SEPARATING LOADS APPLIED TO THE BELLOWS MAINTAIN A CONSTANT LOADING FORCE ON THE MOVING PARTS. DRY-FILM LUBRICANT IS USED TO REDUCE FRICTION AND GALLING. MATING ROTATIONAL SURFACES HAVE TIGHT TOLERANCE CONTROLS TO INCREASE SURFACE CONTACT AREA WHICH REDUCES GALLING, STRESS RISERS, AND OFFSET LOADING. TOLERANCE CONTROLS ALSO DECREASE LUBRICANT WEAR, INCREASING LIFE. INTERNAL STABILIZERS REDUCE TURBULENCE OVER THE BELLOWS ASSEMBLY AND PROVIDES LAMINAR FLOW WHICH INHIBITS FLOW INDUCED VIBRATION. VENT HOLES ARE MANUFACTURED IN THE STABILIZERS TO EQUALIZE PRESSURE ACROSS THE SURFACE. SCREENS KEEP CONTAMINATION FROM COLLECTING IN THE CONVOLUTION AREA IN ADDITION TO EQUALIZING PRESSURE. THE FLEX JOINT HAS COMPLETED BENDING MOMENT, FLEXURAL ENDURANCE, ULTIMATE PRESSURE, PROOF PRESSURE, VIBRATION, AND SECTIONING DVS TESTING (4). MINIMUM FACTORS OF SAFETY FOR THE DUCT MEET CEI REQUIREMENTS (5). LOW CYCLE FATIGUE LIFE FOR THE DUCT MEETS CEI REQUIREMENTS (6). THE DUCT IS HIGH CYCLE FATIGUE LIFE LIMITED BY MAJOR WAIVER (11). FLEX JOINTS ARE HIGH CYCLE FATIGUE LIFE LIMITED BY MAJOR WAIVER (12). THE DUCT ASSEMBLY PARENT MATERIAL WAS CLEARED FOR FRACTURE MECHANICS/NDE FLAW GROWTH BY RISK ASSESSMENT (7). TABLE K102 LISTS ALL THE FMEA/CIL WELDS AND IDENTIFIES THOSE WELDS IN WHICH THE CRITICAL INITIAL FLAW SIZE IS NOT DETECTABLE, AND THOSE WELDS IN WHICH THE ROOT SIDE IS NOT ACCESSIBLE FOR INSPECTION. THESE WELDS HAVE BEEN ASSESSED AS ACCEPTABLE FOR FLIGHT BY RISK ASSESSMENT (8). THE VISUAL BELLOWS INSPECTION, HE MASS LEAK, AND ACCESSIBLE BELLOWS WELDS DYE PENETRANT INSPECTION TEST HAS BEEN COMPLETED ON ENGINES 2010 (9) AND 2014 (10) FLEX JOINTS. NO ANOMALIES WERE FOUND. THE 2010 DUCT HAD ACCUMULATED 65 STARTS AND 19,903 SECONDS. THE 2014 DUCT HAD ACCUMULATED 53 STARTS AND 15,346 SECONDS.

(1) RS008901, RS008921; (2) RSS-8582; (3) I.L. 0126-8066; (4) RSS-511-13; (5) RSS-8546, CP320R0003B; (6) RL00532, CP320R0003B; (7) NASA TASK 117; (8) RSS-8756, MCR 0964; (9) CD#2-0152; (10) CD#2-87-0031; (11) DAR 2227; (12) DAR 2122

SSME FMEA/CIL
INSPECTION AND TEST

Component Group: Ducts and Lines
 CIL Item: K102-02
 Part Number: RS007034
 Component: LPFTP Turbine Drive Duct
 FMEA Item: K102
 Failure Mode: Piece part structural failure.

Prepared: D. Early
 Approved: T. Nguyen
 Approval Date: 7/25/00
 Change #: 1
 Directive #: CCBD ME3-01-5638

Page: 1 of 2

Failure Causes	Significant Characteristics	Inspection(s) / Test(s)	Document Reference
A	STABILIZER		RS008901
	STABILIZER		RS008921
	MATERIAL INTEGRITY	MATERIAL INTEGRITY IS VERIFIED PER DRAWING REQUIREMENTS.	RS008901 RS008921
		THE INCOLOY BAR IS PENETRANT INSPECTED PER SPECIFICATION REQUIREMENTS.	RA0115-116
	HEAT TREAT	HEAT TREAT IS VERIFIED PER SPECIFICATION REQUIREMENTS.	RA0611-020
	SURFACE FINISH	THE STABILIZER DRY-FILM LUBRICATION IS VERIFIED PER DRAWING REQUIREMENTS.	RS008901 RS008921
	ASSEMBLY INTEGRITY	INNER RADII ARE INSPECTED PER DRAWING REQUIREMENTS.	RS008901 RS008921
	SLEEVE		RS008901
	SLEEVE		RS008921
	MATERIAL INTEGRITY	MATERIAL INTEGRITY IS VERIFIED PER DRAWING REQUIREMENTS.	RS008901 RS008921
		THE SLEEVE BAR MATERIAL IS PENETRANT INSPECTED PER SPECIFICATION REQUIREMENTS.	RA0115-116
	HEAT TREAT	HEAT TREAT IS VERIFIED PER SPECIFICATION REQUIREMENTS.	RA0611-020 RA1611-002
	SURFACE FINISH	THE SLEEVE DRY-FILM LUBRICATION IS VERIFIED PER DRAWING REQUIREMENTS.	RS008901 RS008921
	ASSEMBLY INTEGRITY	INNER RADII ARE INSPECTED PER DRAWING REQUIREMENTS.	RS008901 RS008921
	WELDS		RS008901
	WELDS		RS008921
WELD INTEGRITY	ALL WELDS ARE INSPECTED TO DRAWING AND SPECIFICATION REQUIREMENTS PER WELD CLASS. INSPECTIONS INCLUDE: VISUAL, DIMENSIONAL, PENETRANT, RADIOGRAPHIC, ULTRASONIC, AND FILLER MATERIAL, AS APPLICABLE.	RL10011 RA0607-094 RA0115-116 RA0115-006 RA1115-001 RA0115-127	
FLEX JOINT		RS008901	
FLEX JOINT		RS008921	
ASSEMBLY INTEGRITY	THE FLEX JOINT IS GIMBAL TESTED PER DRAWING REQUIREMENTS.	RS008901 RS008921	
	THE FLEX JOINT IS ACCEPTANCE TESTED PER SPECIFICATION REQUIREMENTS.	RL00376 RL00377	
DUCT		RS007034	

Component Group: Ducts and Lines
 CIL Item: K102-02
 Part Number: RS007034
 Component: LPFTP Turbine Drive Duct
 FMEA Item: K102
 Failure Mode: Piece part structural failure.

Prepared: D. Early
 Approved: T. Nguyen
 Approval Date: 7/25/00
 Change #: 1
 Directive #: CCB0 ME3-01-5638

Page: 2 of 2

Failure Causes	Significant Characteristics	Inspection(s) / Test(s)	Document Reference
A	COMPONENT CLEANLINESS	COMPONENT CLEANLINESS IS VERIFIED PER SPECIFICATION REQUIREMENTS.	RA1610-004
	FLIGHT FLOW TESTING	THE EXTERNAL SURFACE IS VISUALLY INSPECTED PRIOR TO EACH LAUNCH. (LAST TEST)	OMRSD V41BU0.030

Failure History: Comprehensive failure history data is maintained in the Problem Reporting database (PRAMS/PRACA)

Reference: NASA letter SA21/88/308 and Rocketdyne letter 88RC09761.

Operational Use: Not Applicable.

SSME FMEA/CIL
WELD JOINTS

Component Group: Ducts and Lines
 CIL Item: K102
 Part Number: RS007034
 Component: LPFTP Turbine Drive Duct
 FMEA Item: K102

Prepared: D. Early
 Approved: T. Nguyen
 Approval Date: 7/25/00
 Change #: 1
 Directive #: CCBD ME3-01-5638
 Page: 1 of 1

Component	Basic Part Number	Weld Number	Weld Type	Class	Root Side Not Access	Critical Initial Flaw Size Not Detectable		Comments
						HCF	LCF	
DUCT	RS007034	31	GTAW	I	X			
DUCT	RS007034	32	GTAW	I	X	X		
DUCT	RS007034	37	GTAW	I	X			
DUCT	RS007034	38	GTAW	I	X	X		
DUCT	RS007034	42	GTAW	I	X	X		
DUCT	RS007034	43	GTAW	I	X	X		
DUCT	RS007034	44,45,48	GTAW	I	X	X		
DUCT	RS007034	46	GTAW	I	X	X		
DUCT	RS007034	47	GTAW	I	X	X		
DUCT	RS007034	49	GTAW	I		X		
DUCT	RS007034	50	GTAW	I				
DUCT	RS007034	51,52	GTAW	I	X			
DUCT	RS007034	53	GTAW	I	X	X		
BELLOWS	RS008888	1-4	GTAW	I				
BELLOWS	RS008888	5,6	EBW	I				
BELLOWS	RS008889	1-4	GTAW	I				
BELLOWS	RS008889	5,6	EBW	I				
FLEX JOINT	RS008901	1-4	EBW	I				
FLEX JOINT	RS008901	5-8	EBW	I	X			
FLEX JOINT	RS008921	1,2	EBW	I		X		
FLEX JOINT	RS008921	3-6	EBW	I	X			