CIL

EMU CRITICAL ITEMS LIST

5/30/2002 SUPERSEDES 12/31/2001

Page 1

Date: 3/27/2002

JAME		FAILURE MODE &		
2ΤΥ	CRIT	CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE
		131FM04		
PRIMARY WATER TANK ASSEMBLY #1, \$2 ITEM 131, ITEM 162	3/1RB	Lever latch assembly fails, CCC.	END ITEM: None. Dual lock provided on latch.	A. Design - The springs are made of 17-7 PH material. The latch material is aluminum 7075 (AMS 4078). The retainer lock spring is designed for 10E+6 operating cycles for a 5138 cycle requirement. The torsion spring is highly stressed; (in excess of yield stress 243,570 psi VS 218,000 psi), however, testing has shown this sprin
SV769592-30 (1)		Springs fracture.	GFE INTERFACE:	does not yield and has been certified to meet its cycle requirement.
			None for single	B. Test - PDA Test -
			failure. Loss of CCC if both springs in	A fit check with a CCC is performed per SEMU-60-010. A CCC is installed in the CCC receptacle area to verify proper fit when installed. At that point, proper latch operation is verified.
			both CCC latches fail; and CCC	Certification Test - Certified for a useful life of 25 years (ref. EMUM1-0106).
			rotates out allowing it to be blown off.	C. Inspection - The one helical compression spring is 100% inspected to meet dimensional and force-displacement requirements. The one torsion spring is 100% inspected to meet dimensional requirements.
			MISSION:	-
			None for single spring failure; failure of	D. Failure History - None.
			second spring has no effect.	E. Ground Turnaround - Checked for non-EET processing per FEMU-R-001, Pre-Flight Inspections and Fina Structural and Leakage. FEMU-R-001 Para 8.2 EMU Preflight KSC Checkout for EET processing.
			CREW/VEHICLE: None for single	F. Operational Use - Crew Response -
			failure. Possible loss	PreEVA and EVA: No response, single failure undetectable by crew or ground. Training - Standard EMU training covers this mode.
			of crewman with loss of CCC	Operational Considerations - Flight rules define go/no go criteria related to EMU ventilation and CO2 contr Flight rules define go/no go criteria related to EMU suit pressure regulation.
			sealing/retenti on if both springs in both latches fail.	EVA checklist procedures verify hardware integrity and systems operational status prior to EVA. Real Time Data system allows ground monitoring of EMU systems.
			1411.	
			TIME TO EFFECT /ACTIONS: Immediate.	
			TIME AVAILABLE: Immediate.	
			TIME REQUIRED:	

CIL EMU CRITICAL ITEMS LIST				5/30/2002 SUP	ERSEDES 12/31/2001	Page 2 Date: 3/27/2002
	NAME	CRIT	FAILURE MODE & CAUSES	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE	
			131FM04	Immediate.		
				REDUNDANCY SCREENS: A-PASS B-FAIL C-PASS		

_

EXTRAVEHICULAR MOBILITY UNIT

SYSTEMS SAFETY REVIEW PANEL REVIEW

FOR THE

I-131 PRIMARY WATER TANK ASSEMBLY

CRITICAL ITEM LIST (CIL)

EMU CONTRACT NO. NAS 9-97150

Prepared by: MS - Project Engineering Approved by:

<u>M. Smyln</u> HS - Reliability

-Rom

HS - Engineering Manager

2-4/11/02

6/12

-702

5/7/02

Freeram Manager