

Document N^o 18901-70131B
 Release Date 10/30/95
 Revision Date 02/26/96
 Page A-27

Failure Modes and Effects Analysis/Critical Items List

FMEA No:	OSS-ST576-13	Originator:	G. Hall/OSS	Project:	STS-76 DTO 671
Part Name:	Hook, Large	ORU Part #	SED33107201-301	Quantity:	1
Part #:	SED33108378-301	ORU Part Name:	Safety Tether Assy	System:	EVA
Drawing:	SED33108378	Subsystem:	N/A	Effectivity:	STS-76

Time to Effect: N/A
 Time to Detect: N/A
 Time to Correct: N/A
 Failure Detection/Flight: N/A

Remarks:

-Retention Rationale-

(A) Design: N/A
 (B) Test: N/A
 (C) Inspection: N/A
 (D) Failure History: N/A
 (E) Operational Use: N/A

Prepared By:	G. Hall/OSS	Revision:	B	Date:	02/26/96
--------------	-------------	-----------	---	-------	----------